

# REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NoR:8102170303 DUC.DATE: 81/02/05 NOTARIZED: NO  
 FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ  
 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ  
 AUTH.NAME AUTHOR AFFILIATION  
 NUNN,D.E. Southern California Edison Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 ENGELKEN,R.H. Region 5, San Francisco, Office of the Director

DOCKET #

05000361

05000362

SUBJECT: Amends 801223 final deficiency rept re cracked coil spools  
 in GE Type HFA relays.Previously reported corrective action  
 will not be performed.All Class IE HFA relays will be  
 replaced w/Century Series HFA relays.

DISTRIBUTION CODE: B019S COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1-----  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:Send all FSAR & ER amends to L Chandler.  
 1 cy:J Hanchett (Region V).D Scaletti,1 cy of all envir info  
 Send all FSAR & ER amends to L Chandler.  
 1 cy:J Hanchett (Region V).D Scaletti,1 cy of all envir info

05000361

05000362

ACTION:	RECIPIENT		COPIES		ACTION:	RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
ACTION:	A/D LICENSNG	04	1		MIRAGLIA,F.	05	1		
	LEE,J.	06	1		ROOD,H.	07	1		
INTERNAL:	AD/RCI/IE	17	1		ASLBP/J.HARD		1		
	O/DIR HUM FAC15		1		DIR,DIV OF LIC		1		
	EDU & STAFF	19	1		EQUIP QUAL BR11		1		
	HYD/GE0 BR	22	1		I&E	09	1		
	LIC QUAL BR	12	1		MPA	20	1		
	NRC PDR	02	1		OELD	21	1		
	PRUC/TST REV	15	1		QA BR	14	1		
	REG FILE	01	1		RUTHERFORD,W.IE		1		
	STANDRDS DEV	21	1						
EXTERNAL:	ACRS	16	16	16	LPDR	03	1		
	NSIC	08	1						

FEB 19 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR

ENCL

40

0

39

39

MM 4

*Southern California Edison Company*

**SCE**

P. O. BOX 800  
2244 WALNUT GROVE AVENUE  
ROSEMEAD, CALIFORNIA 91770

D. E. NUNN  
MANAGER, QUALITY ASSURANCE

February 5, 1981

TELEPHONE  
(213) 572-1695

Mr. R. H. Engelken, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region V  
Suite 202, Walnut Creek Plaza  
1990 North California Boulevard  
Walnut Creek, California 94506

Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362  
San Onofre Nuclear Generating Station, Units 2 & 3

By letter to you dated December 23, 1980, we transmitted a final report in accordance with 10CFR50.55(e) concerning Cracked Coil Spools in General Electric Type HFA relays. In that report we stated that the corrective action would be to replace with Century Series HFA relays all currently used Class IE relays which exhibit cracks or are found to be defective when tested in accordance with General Electric Service Advice Bulletin 152.1.

The purpose of this letter is to amend the final report which was submitted December 23, 1981. The test described by the GE Bulletin will not be performed. All Class IE HFA relays (whether defective or not) will be replaced with Century Series HFA relays.

If you have any questions or require additional information please contact me.

Sincerely yours,



D. E. NUNN

cc: [REDACTED] (NRC, Director I&E)  
R. J. Pate (IRC, San Onofre Units 2 & 3)  
Dr. L. T. Papay

8019  
S  
1/0

S

8102170303