

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8503180256 DOC DATE: 85/03/14 NOTARIZED: NO DOCKET #  
 FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361  
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362  
 AUTH NAME: AUTHOR AFFILIATION  
 MEDFORD, M.O. Southern California Edison Co.  
 RECIP NAME: RECIPIENT AFFILIATION  
 KNIGHTON, G.W. Licensing Branch 3

SUBJECT: Forwards monthly rept describing occurrences resulting in degradation of auxiliary feedwater sys, per License Condition 2.C. Rept covers 850116-0215. Component involved, cause of outage & outage duration listed.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3  
 TITLE: OR Submittal: General Distribution

NOTES: J Hanchett 1cy PDR Documents. ELD Chandler 1cy. 05000361  
 OL:02/16/82  
 J Hanchett 1cy PDR Documents. ELD Chandler 1cy. 05000362  
 OL:11/15/82

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
NRR LB3 BC 01	7 7		
INTERNAL: ACRS 09	6 6	ADM/LFMB	1 0
ELD/HDS2	1 0	NRR/DE/MTEB	1 1
NRR/DL DIR	1 1	NRR/DL/ORAB	1 0
NRR/DL/TSRG	1 1	NRR/DSI/METB	1 1
NRR/DSI/RAB	1 1	REG FILE 04	1 1
RGNS	1 1		

EXTERNAL: LPDR 03	1 1	NRC PDR 02	1 1
NSIC 05	1 1		

NOTES: 2 2

*Southern California Edison Company*



P. O. BOX 800  
2244 WALNUT GROVE AVENUE  
ROSEMEAD, CALIFORNIA 91770

M. O. MEDFORD  
MANAGER, NUCLEAR LICENSING

March 14, 1985

TELEPHONE  
(818) 302-1749

Director, Office of Nuclear Reactor Regulation  
Attention: Mr. George W. Knighton, Branch Chief  
Licensing Branch No. 3  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362  
Auxiliary Feedwater System Monthly Outage Report  
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to License Condition 2.C(26) of Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required monthly report describing any occurrence resulting in the degradation of the Units 2 and 3 Auxiliary Feedwater Systems (AFWS). This report covers the period from January 16, 1985, to February 15, 1985. The component involved, cause of outage, outage duration, and corrective actions taken to return the equipment to operable status are listed.

During the period from January 16, 1985 to January 27, 1985, Unit 3 was operating in Modes 1, 2 or 3 with 100% AFWS availability and a component unavailability of 0%. For the period from January 28, 1985 to February 15, 1985, Unit 3 was in Modes 4 or 5, and for the entire reporting period Unit 2 was in Modes 5, 6 or defueled. For these periods the duration of equipment outages is not specified and the AFWS is not required to be operable per the Technical Specifications.

In accordance with License Condition 2.C(26), our next report will cover the period from February 16, 1985, to March 15, 1985.

If there are any questions regarding this report, please contact me.

Sincerely,

8503180256 850314  
PDR ADDCK 05000361  
R PDR

Enclosure

cc: J. B. Martin (Regional Administrator  
U.S. Nuclear Regulatory Commission, Region V)  
H. Rood (Project Manager SONGS 2/3,  
U.S. Nuclear Regulatory Commission, NRR)

F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)  
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)

Acc  
1/1

San Onofre Nuclear Generating Station, Units 2 and 3  
 Monthly AFWS Outage Report  
 January 16, 1985 to February 15, 1985

Date	Unit	Outage	Duration (hours)	Outage Cause	Corrective Action
01/16/85	2	Preventative Maintenance and Design Change Packages (DCP 127.OM, DCP 1257.OE, DCP 1396.OP, DCP 195.OJ, DCP 6020.OSJ)	--	Auxiliary Feedwater Pumps (P-140; P-504 and P-141) were removed from service to incorporate several design change packages and for miscellaneous surveillances.	None Required

San Onofre Nuclear Generating Station, Units 2 and 3  
 Monthly AFWS Outage Report  
 January 16, 1985 to February 15, 1985

Date	Unit	Outage	Duration (hours)	Outage Cause	Corrective Action
01/31/85	3	Corrective Maintenance	--	Auxiliary Feedwater Pump (P-140) was removed from service to repair steam leak on steam trap (MF535)	Disassembled, cleaned and reassembled