



Carolina Power & Light Company

July 24, 1979

FILE: NG-3513 (R)

SERIAL: GD-79-1882

100-127 AIO: 26

Mr. James P. O'Reilly  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
RESPONSE TO I.E. BULLETIN 79-13

Dear Mr. O'Reilly:

Your Bulletin of June 25, 1979, requested inspection of feedwater system piping for cracking and the submittal of data disclosed by the inspections. This letter documents CP&L's response to Bulletin 79-13.

As you are aware, the Robinson plant inspected its feedwater lines in early June and discovered cracking in the reducers. A meeting was held with the NRC staff in Bethesda, Maryland, on June 27, 1979, to discuss the results of the examinations and the corrective actions then underway. The discussions of the meeting were documented by letter GD-79-1748 to Mr. Albert Schwencer on July 10, 1979. A copy of this letter was telecopied to you on July 11, 1979. In addition, the concerns addressed in item five of Bulletin 79-13 were responded to by letter GD-79-1801 to you on July 18, 1979. These two previously transmitted letters satisfy all of the requirements of Bulletin 79-13, and we therefore consider the bulletin resolved.

We trust that this information is suitable for your use. If you have any questions, please contact my staff.

Yours very truly

B. J. Furr  
Manager

Generation Department

CSB:dcj\*

cc: Mr. Norman C. Moseley

790823 0885

790292  
OFFICIAL COPY