

LICENSEE EVENT REPORT

CONTROL BLOCK:

						①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	H	B	R	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

CON'T

0	1	REPORT SOURCE										60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80
0	1											60	61											68	69											74	75											80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On July 30, 1979, between 0800 and 1000, the hourly fire patrols were not performed

0 3 | as required when portions of the fire detection system were inoperable. These

0 4 | patrols are required by "proposed" Technical Specification 3.14.1.2.b. This con-

0 5 | stitutes a reportable occurrence per Technical Specification 6.9.2.b.

0 6 |

0 7 |

0 8 |

7 8 9

0 9		SYSTEM CODE A B		CAUSE CODE A	CAUSE SUBCODE F	COMPONENT CODE Z Z Z Z Z Z						COMP. SUBCODE Z	VALVE SUBCODE Z
8		9	10	11	12	13	14	15	16	17	18	19	20
LER/RO REPORT NUMBER		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 2 5		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0			
21		22		23		24		25		26			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED			
H		Z		Z		Z		0 0 0 0		Y			
18		19		20		21		22		23			
33		34		35		36		37		40			
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									
N		Z		Z 9 9 9									
24		25		26									
42		43		44									
45		46		47									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The day shift fire patrol failed to report for work. The midnight shift fire patrol
1 1 | left the plant at 0800 without informing the Shift Foreman that he had not been re-
1 2 | lieved. The fire patrol inspections were resumed at 1100 hours that day by an
1 3 | auxiliary operator. The person who failed to report to work will be replaced. The
1 4 | contractor that left has been sternly counselled concerning his responsibilities.

FACILITY STATUS								% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION			
1	5	C	(28)	1	0	0	(29)					A	(31)	Operator Observation				(32)					

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

8 9 10 11 44

45 80

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23</																																																							

	PUBLICITY	(45)	NRC USE ONLY
ISSUED	DESCRIPTION		
8 [] [] 9	[N] (44) NA		
10		68	69 70 71 72 73 74 75 76 77 78 79 80

NRC USE ONLY

R. B. Starkey, Jr.

(803) 383-4524

7908290449

Licensee Event Report 79-25
SERIAL:RSEP/79-826
August 2, 1979

SUPPLEMENTAL INFORMATION
FOR
LICENSEE EVENT REPORT 79-25

1. Cause Description and Analysis:

On July 30, 1979, between 0800 and 1000 hours, the hourly inspections of the fire zones were not performed as required by Technical Specifications, Paragraph 3.14.1.2.b. The contractor person who had been assigned to perform these inspections failed to report to work. The midnight shift fire patrol left the plant without informing the Shift Foreman that he had not been relieved.

2. Corrective Action:

The Shift Foreman assigned one of the Auxiliary Operators to perform the hourly fire inspections for the remainder of the shift.

3. Corrective Action to Prevent Further Occurrence:

The contractor who failed to report for work will be replaced. The Shift Foreman, during the first hour of his shift, will physically verify (i.e. by sight, telephone, or P.A. system) that the person assigned to perform these inspections is present. If he is not present, an auxiliary operator will make the required inspections until a replacement can be found. In addition to these actions, the contractor who left without being relieved has been sternly counselled concerning his responsibilities.