

## SENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	6	1	7	0	7	2	4	7	9	8	0	8	2	3	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

8 9

0 9 8

SYSTEM CODE  
A B (11)

CAUSE CODE  
A (12)

CAUSE SUBCODE  
F (13)

COMP. SUBCODE  
Z (15)

VALVE SUBCODE  
Z (16)

COMPONENT CODE  
Z Z Z Z Z Z (14)

13 18

19 20

LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17		7	9	0 2 4		0 3		L	0								
21		22	23		24	25	26	27	28	29	30	31	32				
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
H		Z		Z		Z		0 0 0 0		Y		N		Z		Z 9 9 9	
18		19		20		21		22		23		24		25		26	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The midnight shift fire patrol failed to report for work due to car trouble. The

1 1 evening shift fire patrol left at midnight without informing the Shift Foreman that

1 2 he had not been relieved. The fire patrols were resumed by the day shift fire patrol

1 3 at 0800. All fire patrols were instructed to inform the Shift Foreman if their relief

1 4 is not present and not to leave until they are relieved.

FACILITY STATUS (28) 5 C 3 0 29 OTHER STATUS (30) METHOD OF DISCOVERY (31) A Operator Observation DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 8 9 Z 33 10 11 NA 44

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

LOSS OF OR DAMAGE TO FACILITY (43)  
 TYPE DESCRIPTION  
 1 9 8 9 10 NA 7908300663

PUBLICITY  
 ISSUED **N** (44) DESCRIPTION **NA** (45)

NAME OF PREPARED R. B. Starkey, Jr.

PHONE: 803-383-4524

Licensee Event Report 79-24  
SERIAL: RSEP/79-826  
August 21, 1979

SUPPLEMENTAL INFORMATION  
FOR  
LICENSEE EVENT REPORT 79-24

1. Cause Description and Analysis:

On July 24, 1979, between 0000 and 0800, the hourly inspections of the fire zones were not performed as required by Technical Specifications, Paragraph 3.14.1,2.b. The contractor person who had been assigned to perform these inspections failed to report to work. He attempted to call the plant but did not have the correct plant phone number. The plant phone number is now unlisted, therefore, he was not able to inform the appropriate personnel. The fire patrol on the evening shift of the previous day left the plant at midnight without informing the Shift Foreman that he had not been relieved. Due to other plant problems, the Shift Foreman failed to realize that the fire inspections were not being performed.

2. Corrective Action:

The inspections were resumed when the day shift person assigned these duties reported to work at 0800.

3. Corrective Action to Prevent Further Occurrence:

Personnel who are assigned these duties have been given the correct plant phone number. They were counselled concerning the necessity of having a continuous fire patrol and were told not to leave the plant until they had been relieved. They were also instructed to notify the Shift Foreman if their relief is not available.