

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S	C	H	B	R	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0	1	REPORT SOURCE		L	6	0	5	0	0	0	2	6	1	7	0	8	1	4	7	9	8	0	9	1	3	7	9	9
7	8			60	61	DOCKET NUMBER								68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	On August 14, 1979, between 0100 and 0530, the hourly fire patrols were not conducted
---	---	---

03 | as required when portions of the fire detection system were inoperable. The patrols

0 4 are required by "proposed" Technical Specification 3.14.1.2.b. This would constitute

0	5	a reportable occurrence per Technical Specification 6.9.2.b.
---	---	--

0	6	
---	---	--

0	7	
---	---	--

0	8	
---	---	--

7 8 9

SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE						COMP. SUBCODE	VALVE SUBCODE
0	9	A	A	F	Z	Z	Z	Z	Z	Z	Z
7	8	9	10	11	12	13	14	15	16	17	

LER/RO REPORT NUMBER (17) [7] [9]		EVENT YEAR [21] [22]		SEQUENTIAL REPORT NO. [23] [24] [25] [26]		OCCURRENCE CODE [27] [28] [29]		REPORT TYPE [30] [31]		REVISION NO. [32]	
ACTION TAKEN [33] [34]		FUTURE ACTION (18) [35] [36]		EFFECT ON PLANT [37] [38] [39]		SHUTDOWN METHOD [40] [41]		HOURS [42] [43] [44] [45]		ATTACHMENT SUBMITTED (22) [46] [47]	
NPRD-4 FORM SUB. [48] [49]		PRIME COMP. SUPPLIER [50] [51] [52]		COMPONENT MANUFACTURER [53] [54] [55] [56]							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The midnight shift fire patrolman failed to conduct the hourly patrols between 0100

[1] [1] and 0530. When asked, he informed the Shift Foreman that he was ill during this time

[1][2] period. He was strictly instructed again on the importance of the hourly patrols and

[1] [3] his responsibilities. The fire patrols were resumed at this time and were performed

1 4 | properly throughout the remainder of the shift.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 1 5 E % POWER 1 0 0 (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (31) A DISCOVERY DESCRIPTION (32) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA	(39)			

PERSONNEL INJURIES					
NUMBER			DESCRIPTION (41)		
1	8		0	0	0 (40) NA

7		8	9	11		12	80
LOSS OF OR DAMAGE TO FACILITY (43)							
		TYPE		DESCRIPTION			
1	9	Z	(42)	NA			

7 8 9 10
PUBLCITY
ISSUED DESCRIPTION (45)
2 0 N (44) NA
7909180345 NRC USE ONLY
80

NAME OF PREPARER R. B. Starkey, Jr.

PHONE: 803-383-4524

7909180345 INRC USE ONLY

LER CONTINUATION - RO# 79-029

Facility: HBR-2

Event Date: 8-14-79

CAUSE DESCRIPTION AND ANALYSIS:

On August 14, 1979, between 0100 and 0530, the hourly inspections of the fire zones were not performed as required by proposed Technical Specifications, Paragraph 3.14.1.2.b. The contractor person who had been assigned to perform these inspections failed to conduct them properly during this time period. Upon investigation, the Shift Foreman learned from the individual that he felt sick and "could not move around very well".

CORRECTIVE ACTION:

The Shift Foreman sternly explained the importance of these hourly inspections and the responsibilities of the fire patrol. He further explained the importance of informing the Shift Foreman if a replacement person is required for any reason. The patrols were resumed and performed properly for the remainder of the shift.

CORRECTIVE ACTION TO PREVENT FURTHER OCCURRENCE:

If the present contractor personnel prove themselves to be unreliable, they are replaced by other, more reliable personnel. No other corrective action is deemed necessary at this time.