



Carolina Power & Light Company

October 30, 1979

NOV 2 9:40

*Central File*  
50-261

FILE: NG-3513 (R)

SERIAL: GD-79-2737

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Region II, Suite 1217  
230 Peachtree Street, NW  
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
SUPPLEMENTAL RESPONSE TO IE BULLETIN NO. 79-04

Dear Mr. O'Reilly:

On October 9, 1979, Mr. T. McHenry of your staff telephoned us with several questions pertaining to our June 1, 1979, response to IE Bulletin 79-04 concerning Velan check valves. Responses to each of Mr. McHenry's questions are given below:

1. Our original examination of Velan swing check valves on safety-related systems did include all valve pressure classes. Our June 1, 1979, submittal erroneously indicated that all of the valves identified were 1500-pound class valves, while in reality the valves are three 2500-pound, three 1500 pound, and one 150 pound class valves.
2. The actual valve weights were supplied by our NSSS vendor, who was their original purchaser by valve tag number, to our Architect-Engineer who performed the reanalysis described in the June 1 letter.
3. Yes, the support modifications mentioned in our June 1 letter were completed prior to startup, at the end of the refueling outage.

We trust that this information is satisfactory to resolve Mr. McHenry's concerns. If you have any further questions, please do not hesitate to contact me.

Yours very truly,  
Original Signed By  
B. J. Furr

B. J. Furr  
Vice President - Generation

CSB/eaj\*

cc: Mr. V. Stello