

FILE: NG-3513 (R)

SERIAL: GD-78-1850


Mr. James P. O'Reilly
U.S. Nuclear Regulatory Commission
Region 2, Suite 1217
230 Peachtree Street
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
RESPONSE TO IE BULLETIN 78-06

Dear Mr. O'Reilly:

In response to your letter of May 31, 1978, transmitting IE Bulletin 78-06 concerning defective Cutler-Hammer, Type M relays with DC coils (Catalog No. D23 MRD), an investigation has been completed that confirmed that no relays of this type are used, or stocked as spares, at the H. B. Robinson Steam Electric Plant, Unit No. 2.

Yours very truly,


E. E. Utley
Senior Vice President
Power Supply

DCS:dcj*

cc: Mr. E. Volgenau

1102

CP