

Letter to N. C. Moseley from Carolina Power and Light Company dated April 11, 1975.

DISTRIBUTION:

50-261

Reply to IEB - 75-03

H. D. Thornburg, IE

IE:HQS (5)

Office of Standards Development

Central Files

Division of Reactor Licensing (13)

J. Rizzo, OMIPC

PDR

Local PDR

NSIC

TIC

Chief, Regulatory News Branch, OIS, HQs

AO
(2)



Carolina Power & Light Company

April 11, 1975

FILE: NG-3513 (R)

SERIAL: NG-75-524

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N. W.
Atlanta, Georgia 30303


Dear Mr. Moseley:

H. B. ROBINSON NO. 2
LICENSE NO. DPR-23
BULLETIN IE 75-03
INCORRECT OPERATION OF ASCO SOLENOID VALVES

In accordance with IE Bulletin No. 75-03, an investigation at H. B. Robinson No. 2 revealed no solenoids of series 8300C, 8302C types F, U, RF or RU in the primary or any other safety related system.

Three valves of this series were found on the secondary system in nonsafety related applications, and five of the subject valves and nine repair kits are presently in stock. These stock items were marked for use in only nonsafety related applications April 7, 1975, and will be controlled in accordance with the Robinson Continuing Quality Assurance Plan.

Yours very truly,


E. E. Utley
Vice President
Bulk Power Supply

DBW:pn

cc: Mr. N. B. Bessac
Mr. P. W. Howe
Mr. R. E. Jones
Mr. J. B. McGirt
Mr. D. B. Waters