

Letter to N. C. Moseley from Carolina Power and Light Company dated April 1, 1975.

DISTRIBUTION:

50-261

H. D. Thornburg, IE

IE:HQS (5)

Office of Standards Development

→ Central Files

Division of Reactor Licensing (13)

PDR

Local PDR

NSIC

TIC

STATE



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina

April 1, 1975

Robinson File No. 2-0-4-a-1

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N.W. -
Atlanta, Georgia 30303

Mr. Donald Knuth, Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Washington, D. C. 20545

Dear Sirs:

"B" EMERGENCY DIESEL LOW LUBE OIL PRESSURE TRIP

In accordance with Section 6.6.2 of the Technical Specification, the following abnormal occurrence is reported.

At 1655 hours, March 31, 1975 "B" Emergency Diesel was started to perform weekly P.T.-23.1. At 1657 hours the diesel tripped due to low lube oil pressure. An inspection revealed a high Δp across the lube oil filters. "A" diesel was test operated satisfactorily at this time. "B" diesel filters were changed and the unit returned to service at 2032.

The diesel failure constitutes an abnormal occurrence as defined in Technical Specification 1.8.d and was reported to Mr. Frank Long of DRO by telephone on April 1, 1975.

Yours very truly,

Jack R. McGirt, Manager
H. B. Robinson SEO Plant

RWL:gg