

8-13-73

50-261

2-0-4-a

CAROLINA POWER AND LIGHT
PO BOX 790
HARTSVILLE SC

4704

8033321351 TDMT HARTSVILLE SC 91 08-06 0145P EST
PMS MR NORMAN C NOSELEY DIRECTOR, DIRECTORATE OF REGULATORY OPERATIONS
DLR


230 PEACHTREE ST
ATLANTA, GA 30303

IN ACCORDENCE WITH SECTION 6.6.2.A OF THE TECHNICAL SPECIFICATIONS,
THE FOLLOWING ADNORMAL ACCORDANCE IS REPORT.

DUE TO AN ERROR IN THE INITIAL VOLUME CALCULATION OF THE SAFETY
INJECTIONS ACCUMULATORS SLIGHTLY LEFT THAN REQUIRED VOLUMES HAVE
NEED EXPERIENCED BY THE REACTOR WAS OPERATING AT TOWER. THE
MINIMUM LEVELS DURING THESE PERIODS WERE APPROXIMATELY 99.3
PER CENT OF THAT WHICH IS REQUIRED BY THE TECHNICAL SPECIFICATION.
NEW ALARMS SET POINTS HAD BEEN ESTABLISHED TO PREVENT RECURRENCE
OF THIS PROBLEM.

THIS WAS REPORTED TO MR BILL SIEDLE OF D.R.C. BY TELEPHONE ON
AUG. 6TH 1973.

BENNY J. FURK MANAGER H.B. ROBINSON SEG PLANTS



Telegram from Carolina Power and Light Company, Benny J. Furr,
dated August 22, 1973 - 50-261

AUG 29 1973

DISTRIBUTION:

H. D. Thornburg, RO (2)

RO:HQ (5)

→ DR Central Files

Regulatory Standards (3)

Directorate of Licensing (13)

PDR

Local PDR

NSIC

OIS, OR

State