



Telegram

TBD319(1537)(2-080704E191)PD 07/10/73 1537

50 - 261

ICS IPMMTZZ CSP

8033321351 TDMT HARTSVILLE SC 133 07-10 0337P EST

FON 4045264503

NORMAN C MOSELEY, FONE AND MAIL

DIRECTOR REGION 2 AEC DIRECTORATE OF REGULATORY OPERATION 230

PEACHTREE ST *Suite 818*

ATLANTA GA 30303

IN ACCORDANCE WITH SECTION 6.6.2 OF THE TECHNICAL SPECIFICATIONS THE FOLLOWING ABNORMAL OCCURRENCE IS REPORTED AT 0830 ON JULY 10 WHILE ROUTINELY PUTTING CONTAINMENT FOR COOLER NUMBER TWO IN SERVICE, THE CIRCUIT BREAKER FOR THIS FAN TRIPPED. INVESTIGATION REVEALED THAT THE TRIP WAS INITIATED BY INSTANTANEOUSLY OVER OCCURRENCE CAUSED BY THE MISALIGNMENT OF THE INSTANTANEOUSLY CALIBRATION SPRING IN THE OVER CURRENT TRIP DEVICE. THE DEVICE WAS REMOVED, THE SPRING REALIGNED AND THE COOLING UNIT PUT IN

F-1201 (R5-69)

SERVICE SATISFACTORILY AT 1007. TO PREVENT THE RECURRENCE OF THIS TRIP, ALL NEWLY INSTALLED TRIP DEVICES ARE BEING VISUALLY INSPECTED FOR PROPER SPRING ALIGNMENT. THIS UNIT HAD OPERATED SATISFACTORILY FOLLOWING THE INSTALLATION OF THE NEW TRIP DEVICE. THIS WAS REPORTED TO MR HERB WHITTNER IN PERSON ON JULY 10, 1973.

BENNY J FURR MANAGER H B ROBINSON SEG PLANT PO BOX 790 HARTSVILLE SC 29550

3F-1201 (R5-69)

JUL 17 1973

Telegram from Carolina Power and Light Company, Benny J. Furr,  
dated July 10, 1973 - 50-261

DISTRIBUTION:

H. D. Thornburg, RO (2)

RO:HQ (5)



DR Central Files

Regulatory Standards (3)

Directorate of Licensing (13)

PDR

Local PDR

NSIC

OIS, OR

State