

A002

REGULATORY INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-261 H B ROBINSON 2
RECIPIENT: O'REILLY, J.P.
ORIGINATOR: BANKS, H.R.
COMPANY NAME: CAROLINA PWR & LIGHT
SUBJECT:

DOC DATE: 781101
ACCESSION NBR: 7811090186
COPIES RECEIVED:
LTR 1 ENCL 1
SIZE: 1+1

LER#78-025/03L-0 on 781003: during normal oper PPS leakage past Containment Purge Outlet isolation valve 50 FR was in excess of Tech Spec limits due to normal wear of Nordel rubber seat.

DISTRIBUTION CODE: A002
DISTRIBUTION TITLE:
INCIDENT REPORTS

NOTARIZED

NAME	ENCL?
BR CHIEF	W/4 ENCL
REG FILE	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION


ORB#1 BC

TOTAL NUMBER OF COPIES REQUIRED:
LTR
ENCL

42
42

NOTES:

NOV 14 1978



Carolina Power & Light Company
November 1, 1978

FILE: NG-3516 (R)

SERIAL: GD-78-2917

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 78-025

Dear Mr. O'Reilly:

In accordance with Section 6.9.2.b of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July, 1977.

Yours very truly,

H. R. Banks
Manager
Nuclear Generation

DCS:jpw*

Attachment

cc: Messrs. R. A. Hartfield
J. G. Davis

REGULATORY DOCKET FILE COPY

78/1090186

A002
5/11