



Carolina Power & Light Company

April 13, 1979

79 APR 16 P 2: 48

Ental File
50-261

FILE: NG-3513 (R)

SERIAL: GD-79-1000

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
RESPONSE TO IE BULLETIN 79-03

Dear Mr. O'Reilly:

Bulletin 79-03, March 12, 1979, requested information concerning longitudinal weld defects in pipe spools manufactured by Youngstown Welding and Engineering Company.

A review of records by the plant, the NSSS supplier and the Architect-Engineer have all indicated that no pipe spools by this supplier were or are planned to be utilized in the H. B. Robinson Plant. A detailed review of subcontractors' records is still underway, and in the unlikely event that this review indicates that any of the material is in use, CP&L will promptly notify you and provide all of the necessary additional data.

Yours very truly,

M A M. Duff

for E. E. Utley
Senior Vice President
Power Supply Group

CSB:jmb*

cc: NRC Office of Inspection and Enforcement
Division of Reactor Construction Inspection
Washington, D. C. 20555

ao2
ccp

790090

OFFICIAL COPY