

November 6, 1978

NOV 9 AIO: 47

FILE: NG-3513 (R)

SERIAL: GD-78-2946

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
RESPONSE TO IE INSPECTION REPORT NO. 50-261/78-18

Dear Mr. O'Reilly:

We have received and reviewed the subject report and are hereby responding to the deviation identified:

Deviation: The licensee's response to IE Report No. 50-261/77-7, dated November 29, 1977, states that HP-30 will be strictly adhered to in inventorying emergency kits.

Contrary to the above commitment, on August 7, 1978, the inspector observed at the Plant Access Emergency Kit: (1) two survey instruments with batteries left in, and (2) quantities of half-face and full-face respirators that deviated from the approved inventory list.

Corrective Action: The batteries were removed from the two survey instruments noted, and the proper quantities of each type of respirator were placed in the emergency kit as shown on the approved inventory list.

Corrective Action To Prevent Further Deviation: The procedure for inventorying emergency kits (HP-30) has been changed into a Periodic Test (PT-43) which will be performed monthly. The personnel performing this periodic test will be required to initial each item and/or instruction specified on the inventory for each emergency kit. This will provide more positive control over the inventorying of emergency kits.

7812070065


Mr. James P. O'Reilly

-2-

November 6, 1978

Date When Correction Of The Deviation Will Be Achieved: Full compliance was achieved on August 28, 1978.

Very truly yours,


B. J. Furr
Manager
Generation

HSZ/DCS:jnh*