

August 21, 1980

307 29 P12:00

FILE: NG-3513(R)

SERIAL: NO-80-1230

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET 50-261  
LICENSE NO. DPR-23  
RESPONSE TO BULLETIN 80-20 - FAILURES OF W-2 SWITCHES

Dear Mr. O'Reilly:

The review of Westinghouse Type W-2 switches, as requested by your bulletin, was conducted when the technical bulletin was received from Westinghouse. This investigation revealed that no Westinghouse Type W-2 switches, incorporating the use of a normally closed contact in the neutral or automatic start position, are used in safety-related applications on H. B. Robinson Unit No. 2.

If you have any questions concerning this information, please contact me or a member of my staff.

Yours very truly,

*W. J. Furr*

B. J. Furr  
Vice President  
Nuclear Operations

MVP:CSB:tma\*

cc: Mr. N. C. Moseley