



Carolina Power & Light Company

September 30, 1980

USNRC REGION II
ATLANTA, GEORGIA

30 OCT 6 AM : 04

FILE: NG-3513 (R)

SERIAL: NO-80-1374

Mr. James P. O'Reilly, Director
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
VALUE/IMPACT INFORMATION
IE BULLETINS 80-15, 16, 19, 20

Dear Mr. O'Reilly:

As a result of administrative oversight, information requested regarding manpower expended for review, preparation of response and corrective actions related to the subject Bulletins was omitted. Your staff was notified of this omission on September 11, 1980, and agreed to accept this information as a separate response. Accordingly, following are the estimates for each Bulletin:

IEB - 80-15: Possible Loss of Hotline with Loss of Off-Site Power

Review and Preparation - 50 manhours (includes estimate for future testing)
Corrective Actions - 0 manhours

IEB - 80-16: Potential Misapplication of Rosemount, Inc., Models 1151 and 1152 Pressure Transmitters with Either "A" or "D" Output Codes

Review and Preparation - 34 manhours
Corrective Actions - 0 manhours

IEB - 80-19: Failures of Mercury Wetted Matrix Relays in Reactor Protective Systems of Operating Nuclear Power Plants Designed by Combustion Engineering

Review and Preparation - 24 manhours
Corrective Actions - 0 manhours


September 30, 1980

IEB - 80-20: Failures of Westinghouse Type W-2 Spring Return
to Neutral Control Switches

Review and Preparation - 32 manhours
Corrective Actions - 0 manhours

If you have any questions regarding this information, please
contact my staff.

Very truly yours,



B.J. Furr
Vice President
Nuclear Operations Department

JMC/tma*

cc: Mr. N. C. Moseley