

REGULATORY DOCKET FILE COPY

December 8, 1980

Central File
DEC 16 PM 3 40
DISTRIBUTION
SERVICES UNIT
NRC
OPERATION SERVICES
BRANCH

FILE: NG-3513 (R)

SERIAL: NO-80-1809

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT
UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
RESPONSE TO BULLETIN 80-21
VALVE YOKES SUPPLIED BY MALCOLM FOUNDRY COMPANY, INC.


Dear Mr. O'Reilly:

The review of all active safety-related valves, as requested by your bulletin, has been completed. All active safety-related valves were identified and each valve manufacturer was contacted. None of the manufacturers had purchased yokes from Malcolm Foundry Company except Anchor Darling. Anchor Darling indicated that none of the valves supplied to H. B. Robinson Unit No. 2 have yokes from Malcolm Foundry Company. In summary, no active safety-related valves at H. B. Robinson Unit No. 2 have yokes manufactured by Malcolm Foundry Company, Inc.

This IE Bulletin response required 40 man-hours of H. B. Robinson Plant personnel time.

If you have any questions concerning this information, please contact me or a member of my staff.

Very truly yours,



B. J. Furr
Vice President
Nuclear Operations Department

SHC:kbb*

cc: Mr. N. C. Moseley

Q 8012810396