

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9002080020 DOC.DATE: 90/01/26 NOTARIZED: YES DOCKET #
 FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH.NAME AUTHOR AFFILIATION
 CUTTER,A.B. Carolina Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards response to NRC Bulletin 89-003, "Potential Loss of Required Shutdown Margin During Refueling Operations."

DISTRIBUTION CODE: IE29D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
 TITLE: Bulletin 89-03, Potential Loss of Required Shutdown Margin During Refu

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 LA	1 0	PD2-1 PD	1 1
	LO,R	1 1		
INTERNAL:	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	KOPP,LARRY	1 1	LABARGE,DAVE	1 1
	NRR/DET/ECMB 9H	2 2	NRR/DET/EMEB9H3	1 1
	NRR/DOEA/OEAB11	1 1	NRR/DOEA/OGCB11	1 1
	NRR/DREP/PEPB9D	1 1	NRR/DST 8E2	1 1
	NRR/PMAS/TERB12	1 1	NUDOCS-ABSTRACT	1 1
	REG FILE 02	1 1	RES/DSIR/EIB	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 21

10/11



Carolina Power & Light Company

P.O. Box 1551 • Raleigh, N.C. 27602

JAN 26 1990

A. B. CUTTER
Vice President
Nuclear Services Department

SERIAL: NLS-90-024
10CFR50.

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555


H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
RESPONSE TO NRC BULLETIN 89-03

Gentlemen:

Carolina Power & Light Company (CP&L) hereby responds to NRC Bulletin 89-03, "Potential Loss of Required Shutdown Margin During Refueling Operations," for the H. B. Robinson Steam Electric Plant, Unit No. 2 (HBR2). The Bulletin requested that licensees take specific actions to prevent potential violations of required shutdown margin and inadvertent criticality during refueling caused by improper movement and placement of highly reactive fuel during refueling operations. The HBR2 response to the specific actions requested by this Bulletin is attached.


Please refer any questions regarding this submittal to Mr. John Eads at (919) 546-4165.

Yours very truly,


A. B. Cutter

JHE/jhe
Attachment


A. B. Cutter, having been first duly sworn, did depose and say that the information contained herein is true and correct to the best of his information, knowledge and belief; and the sources of his information are officers, employees, contractors, and agents of Carolina Power & Light Company.


Notary (Seal)

My commission expires: 7/12/94

9002080020 900126
PDR ADOCK 05000261
Q FDC

IF29
11



Document Control Desk
NLS-90-024 / Page 2

cc: Mr. S. D. Ebnetter
Mr. L. Garner (NRC-HBR)
Mr. R. Lo

RESPONSE TO SPECIFIC ACTIONS OF NRC BULLETIN 89-03
"POTENTIAL LOSS OF REQUIRED SHUTDOWN
MARGIN DURING REFUELING OPERATIONS"

Action No. 1 - Assure that any intermediate fuel assembly configuration (including control rods) intended to be used during refueling is identified and evaluated to maintain sufficient refueling boron concentration to result in a minimum shutdown margin of approximately 5%.

HBR2 Response - Procedures to ensure that any intermediate fuel assembly configuration (including control rods) intended to be used during refueling is identified and evaluated to maintain a boron concentration that results in a minimum shutdown margin of 5 percent will be in place prior to fuel handling activities in the next refueling outage, currently scheduled for September, 1990.

Action No. 2 - Assure that fuel loading procedures only allow those intermediate fuel assembly configurations that do not violate the allowable shutdown margin and that these procedures are strictly adhered to.

HBR2 Response - Fuel handling procedures will be revised to reflect Westinghouse guidelines to assure adequate shutdown margin is maintained during refueling operations. Procedure revisions will be in place prior to fuel handling activities in the next refueling outage.

Action No. 3 - Assure that the staff responsible for refueling operations is trained in the procedures recommended in Item 2 above and understand the potential consequences of violating these procedures. This training should include the fundamental aspects of criticality control with higher enriched fuel assemblies.

HBR2 Response - Personnel involved in refueling operations will have received the required training prior to performing fuel handling activities commencing with the next refueling outage.