

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 5438

FILE: _____

FROM: Carolina Power & Light Co. Hartsville, S. C. Benny J. Furr			DATE OF DOC 7-10-73	DATE REC'D 7-13-73	LTR	MEMO	RPT	OTHER TWX
TO: John F. O'Leary			ORIG 1	CC	OTHER	SENT AEC PDR _____ X SENT LOCAL PDR _____ X		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		
	XX							

DESCRIPTION:
TWX, reporting an abnormal occurrence on 7-10-73, in which the circuit breaker for cooler number two fan tripped.....

ENCLOSURES:

ACKNOWLEDGED
Do Not Remove

PLANT NAME: H. B. Robinson Unit No. 2

FOR ACTION/INFORMATION

7-16-73

AB

BUTLER(L)	SCHWENCER(L)	ZIEMANN(L)	REGAN(E)
W/ Copies	W/ Copies	W/ Copies	W/ Copies
CLARK(L)	STOLZ(L)	DICKER(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
GOLLER(L)	VASSALLO(L)	KNIGHTON(E)	
W/ Copies	W/ Copies	W/ Copies	W/ Copies
KNIEL(L)	✓ SCHEMEL(L)	YOUNGBLOOD(E)	
W/ Copies	W/7 Copies	W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ <u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>LIC ASST</u>	<u>A/T IND</u>
✓ AEC PDR	✓ HENDRIE	GRIMES	BROWN (E)	BRAITMAN
✓ OGC, ROOM P-506A	SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSSO	✓ PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓ SHAO		MAIGRET (L)	DUBE
MOORE (L)(BWR)	✓ STELLO	<u>ENVIRO</u>	SERVICE (L)	
DEYOUNG(L)(PWR)	✓ HOUSTON	MULLER	SHEPPARD (E)	<u>INFO</u>
✓ SKOVHOLT (L)	✓ NOVAK	DICKER	SMITH (L)	C. MILES
P. COLLINS	✓ ROSS	KNIGHTON	✓ TEETS (L)	
	✓ IPPOLITO	YOUNGBLOOD	WADE (E)	✓ B. KING(REG OPR E/W
<u>REG OPR</u>	✓ TEDESCO	REGAN	WILLIAMS (E)	Bldg, OGE)
✓ FILE & REGION(3)	✓ LONG	PROJECT LDR	WILSON (L)	
✓ MORRIS	✓ LAINAS			
✓ STEELE	✓ BENAROYA	<u>HARLESS</u>		
	✓ VOLLMER			

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR Hartville, S. C.	(1)(2)(9)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓ 1 - DTIE(ABERNATHY)	1-R.Schoonmaker, OC, GT, D-323	1-GERALD LELLOUCHE
✓ 1 - NSIC(BUCHANAN)	1-R. CATLIN, E-256-GT	BROOKHAVEN NAT. LAB
1 - ASLB(YORE/SAYRE/	1-CONSULTANT'S	1-AGMED(WALTER KOESTER
WOODARD/"H" ST.	NEWMARK/BLUME/AGBABIAN	RM-C-427-GT
✓ 16 - CYS ACRS HOLDINGS	1-GERALD ULRIKSON...ORNL	1-RD...MULLER...F-309 GT
SENT TO LIC ASST. S. TEETS ON 7-16-73		

Regulatory

File Cy.

MGMWSHB WSH

2-055322B191-001 07/10/73

ICS SOTOIPF MLTN

SUSPECTED DUPLICATE 2-080887E191 ICS IPMMTZZ CSP

8033321351 MGM TDMT HARTSVILLE S 152 07-10 0340P EST

ZIP 20545


western union

Mailgram



50-261

JOHN F OLEARY
DIRECTORATE OF LICENSING USAEC
WASHINGTON DC 20545




IN ACCORDANCE WITH SECTION 6.6.2 OF THE TECHNICAL SPECIFICATIONS THE FOLLOWING ABNORMAL OCCURRENCE IS REPORTED AT 0830 ON JULY 10 WHILE ROUTINELY PUTTING CONTAINMENT FOR COOLER NUMBER TWO IN SERVICE, THE CIRCUIT BREAKER FOR THIS FAN TRIPPED. INVESTIGATION REVEALED THAT THE TRIP WAS INITIATED BY INSTANTANEOUSLY OVER OCCURRENCE CAUSED BY THE MISALIGNMENT OF THE INSTANTANEOUSLY CALIBRATION SPRING IN THE OVER CURRENT TRIP DEVICE. THE DEVICE WAS REMOVED, THE SPRING REALIGNED AND THE COOLING UNIT PUT IN SERVICE SATISFACTORILY AT 1007. TO PREVENT THE RECURRENCE OF THIS TRIP, ALL NEWLY INSTALLED TRIP DEVICES ARE BEING VISUALLY INSPECTED FOR PROPER SPRING ALIGNMENT. THIS UNIT HAD OPERATED SATISFACTORILY FOLLOWING THE INSTALLATION OF THE NEW TRIP DEVICE. THIS WAS REPORTED TO MR HERB WHITTNER IN PERSON ON JULY 10, 1973.

BENNY J FURR MANAGER H B ROBINSON SEG PLANT PO BOX 790 HARTSVILLE SC 29550

2041 EST

MGMWSHB WSH



5438