

50-261

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:

Mr. Norman C. Moseley

FROM:

Carolina Power & Light Company
Raleigh, North Carolina
H. R. Banks

DATE OF DOCUMENT

7/11/77

DATE RECEIVED

7/22/77

☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

☒ ORIGINAL
☐ COPY☒ UNCLASSIFIED

1 SIGNED

DESCRIPTION

ENCLOSURE

Licensee Event Report (RO 50-261/2-77-10)
on 6/10/77 concerning CV Purge Outlet inner valve
valve being declared inoperable.....

PLANT NAME:

Robinson Unit No. 2
RJL 7/22/77

(1-P)

ACKNOWLEDGED

DO NOT REMOVE

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

BRANCH CHIEF:
W/ 3 CYS FOR ACTION
LIC ASST.:

Reid (4)

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

KNIGHT

BUTLER

HANAUER

TEDESCO

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/ J. COLLINS

ROSA

EXTERNAL DISTRIBUTION

LPDR: Hartsueth, SC
TIC:
NSIC:
ACRS (16) SENT AS CAT. B

CONTROL NUMBER

772030243



Carolina Power & Light Company

Regulatory

File Cy


July 11, 1977

FILE: NG-3516 (R)

Serial: NG-77-784

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 2-77-10



Dear Mr. Moseley:

In accordance with Section 6.9.2.b of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the attached Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Yours very truly,

H. R. Banks
Manager
Nuclear Generation

WH:pp

Attachment

cc: Mr. W. G. McDonald
Mr. E. Volgenau

772030243

LICENSEE EVENT REPORT

Regulatory

File Cy

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE
NAME

LICENSE NUMBER

LICENSE
TYPE

EVENT
TYPE

01 | S | C | H | B | R | 2 |

0 0 - 0 0 0 0 0 0 - 0 0

4 1 1 1 0

0 3

01 CONT | CATEGORY | REPORT TYPE | REPORT SOURCE | DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION

02 | CV Purge Outlet inner valve was declared inoperable, following a purge operation, due
03 | to excessive PPS leakage past seat. The outer valve was shut while adjustments were
04 | made to the inner valve seat. Following repair and successful pressurization of
05 | the valves' inner space, the inner valve was declared operable. (R0-77-10)
06 |

07 | SYSTEM CODE | CAUSE CODE | COMPONENT CODE | PRIME COMPONENT SUPPLIER | COMPONENT MANUFACTURER | VIOLATION

CAUSE DESCRIPTION

08 | The excessive leakage through the Allis-Chalmers 42"-50FR Streamseal butterfly valve
09 | resulted from normal wear to the rubber seat. Adjustments in reducing this leakage
10 | to the seat ring were successful.

11 | FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION

12 | FORM OF ACTIVITY RELEASED | CONTENT OF RELEASE | AMOUNT OF ACTIVITY | LOCATION OF RELEASE

PERSONNEL EXPOSURES

13 | NUMBER | TYPE | DESCRIPTION

PERSONNEL INJURIES

14 | NUMBER | DESCRIPTION

OFFSITE CONSEQUENCES

15 | NA

LOSS OR DAMAGE TO FACILITY

16 | TYPE | DESCRIPTION

PUBLICITY

17 | NA

ADDITIONAL FACTORS

18 | NA

19 |

NAME: J. B. McGirt PHONE: 803-332-1351

RECEIVED DOCUMENT
PROCESSING UNIT

1977 JUL 22 PM 12 42