

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)

CONTROL NO: 3407

FROM: Carolina Power & Light Co. Raleigh, N.C. 27602 E.E. Utley	DATE OF DOC: 6-16-72	DATE REC'D 6-21-72	LTR X	MEMO	RPT	OTHER
TO: Mr. Edward J. Bloch	ORIG 1	CC	OTHER	SENT AEC PDR <input checked="" type="checkbox"/> SENT LOCAL PDR <input checked="" type="checkbox"/>		
CLASS: <b>U</b> PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-261			

DESCRIPTION: Ltr rpt a problem when the "A" containment spray pump would not rotate freely when turned by hand.....

ENCLOSURES:

PLANT NAMES: H.B. Robinson Plant Unit 2

**DO NOT REMOVE  
ACKNOWLEDGED**

FOR ACTION/INFORMATION

DL 6-21-72

BUTLER(L) W/ Copies	KNIEL(L) W/ Copies	VASSALLO(L) W/ Copies	ZIEMANN(L) W/ Copies	KNIGHTON(ENVIRO) W/ Copies
CLARK(L) W/ Copies	SCHWENCER(L) W/ Copies	H. DENTON W/ Copies	CHITWOOD(FM) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	STOLZ(L) W/ Copies	✓ SCHEMEL(L) W/9 Copies	DICKER(ENVIRO) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ <b>REG FILES</b>	✓ STELLO-L	✓ VOLLMER-L	KARAS-L L/A PWR
✓ AEC PDR	✓ MOORE-L	✓ DENTON-I (4)	MASON-L L/A BWR
✓ REG OPER (2)	✓ LANGE-L	GRIMES-L	BROWN-L L/A PWR
✓ OGC-RM P-506	✓ PAWLICKI-L	GAMMILL-L	WILSON-L L/A PWR
✓ MUNTZING & STAFF	✓ THOMPSON-L	KNIGHTON-ENVIRO	KARI-L L/A BWR
GIAMBUSSO-L	✓ TEDESCO-L	DICKER-ENVIRO	SMITH-L L/A BWR
✓ BOYD-L-BWR	✓ LONG-L	PROJ LDR ENVIRO:	GEARIN-L L/A BWR
✓ DEYOUNG-L-PWR	✓ LAINAS-L		DIGGS-L L/A
MULLER-L-ENVIRO	SHAO-L	SALTZMAN-IND.	TEETS-L L/A
✓ SKOVHOLT-L-OPER	✓ BENAROYA-L	McDONALD-PLANS	WADE-L L/A ENVIRO
✓ KNUTH-L	✓ MORRIS-RO	NUSSBAUMER-FM	BRAITMAN-A/T
✓ MACCARY-L	DUBE-L	SMILEY-FM	HARLESS-ENVIRO
✓ SCHROEDER-L	✓ E. CASE-L	P. COLLINS-L	<b>M. Steele</b>

EXTERNAL DISTRIBUTION

✓ 1-LOCAL PDR Hartville, S.C.	9-NATIONAL LAB'S ANL/ORNL/BNWL	1-SAN/LA/NY--PDR
✓ 1-DTIE-(LAUGHLIN)	1-R. CARROLL-OC, GT	1-CHIEF WATER REACTORS
✓ 1-NSIC-(BUCHANAN)	1-R. CATLIN, A-170, GT	1-RD....E. HALL F-309 GT
1-ASLB-YORE/SARYE WOODWARD/H. ST.	1-CONSULTANT'S NEWMARK/BLUME/AGBABIAN	
✓ 1-C. MILES-C-459, GT	1-DR. GERALD S. LELLOUCHE	
✓ 16 CYS ACRS-HOLDING	BROOKHAVEN NATIONAL LAB	

Regulatory

File Cy:

# Carolina Power & Light Company


Raleigh, North Carolina 27602

June 16, 1972

50-261

Robinson File No. 2-0-4-a

Mr. Edward J. Block, Acting Director  
Directorate of Licensing  
U. S. Atomic Energy Commission  
Washington, D. C. 20545



H. B. ROBINSON UNIT NO. 2  
License DPR-23  
BINDING OF "A" CONTAINMENT SPRAY PUMP

Dear Mr. Block:

In accordance with Paragraph 6.6.1.c, Technical Specifications, the following abnormal occurrence is reported.

While performing a routine equipment check it was discovered that "A" containment spray pump would not rotate freely when turned by hand. The pump was disassembled and inspected. It was found that the impeller alignment ring was galled and binding on the casing alignment seal ring. A new impeller, impeller alignment seal ring and casing alignment ring were installed. The pump was reassembled and test run satisfactorily. This is documented in Periodic Test No. 2.3 performed on June 7, 1972.

The reactor was shutdown during this period for repairs not related to the above problem.

Yours very truly,

E. E. Utley  
Manager  
Bulk Power Supply

JBM/kf

cc: Mr. C. D. Barham  
Mr. N. B. Bessac  
Mr. B. J. Furr

3407