

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9907200001 DOC. DATE: 99/07/13 NOTARIZED: NO DOCKET #
FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
AUTH. NAME AUTHOR AFFILIATION
MCCOLLUM, W.R. Duke Power Co.
RECIP. NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Provides rept of number of tubes plugged or repaired during
SG tube inservice insp for facility cycle 18 refueling
outage as required by TS 5.6.8.a.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 3
TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	LPD2-1 LA	1 1	LABARGE, D	1 1
INTERNAL:	ACRS	1 1	FILE CENTER 01	1 1
	NUDOCS-ABSTRACT	1 1	OGC/RP	1 0
	RES/DET/ERAB	1 1	RES/DET/MEB	1 1
EXTERNAL:	LITCO ANDERSON	1 1	NOAC	1 1
	NRC PDR	1 1		

MICROFILMED

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 11 ENCL 0



W. R. McCollum, Jr.
Vice President

Duke Power

Oconee Nuclear Site
7800 Rochester Highway
Seneca, SC 29672
(864) 885-3107 OFFICE
(864) 885-3564 FAX

July 13, 1999

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Duke Power Company Oconee Nuclear Station, Unit 1
Docket No. 50-269
Steam Generator Inservice Inspection
Steam Generator Tube Plugging and Repair 30-day Report

As required by Technical Specification 5.6.8, a, this letter provides the number of tubes plugged or repaired during the Steam Generator (SG) Tube Inservice Inspection for the Unit 1 Cycle 18 refueling outage. 100% of the Unit 1 SG Tubes were inspected with bobbin current testing.

Seven tube plugs made of Inconel 600 were replaced with plugs made of Inconel 690: One plug was replaced in SG "A" and six plugs were replaced in SG "B". There were no tubes repaired by sleeving in either steam generator. The tables below identify the number of tubes removed from service by plugging and the number of tubes repaired by rerolling in the upper tubesheet.

Steam Generator

Number of Tubes Plugged

A	66
B	189

Steam Generator

Number of Tubes Rerolled

A	38
B	*304

* 304 of these tubes remain in service, four were plugged.

9907200001 990713
PDR ADOCK 05000269
G PDR

1/0


A047

USNRC Document Control Desk
July 13, 1999

Page 2

If there are any questions you may contact R. C. Douglas at
(864) 885-3073.

Very Truly Yours,



W. R. McCollum, Jr.
Site Vice President

USNRC Document Control Desk
July 13, 1999

Page 3

cc: Mr. L. A. Reyes
Regional Administrator, Region II

Mr. M. A. Scott
Senior Resident Inspector

Mr. D. E. Labarge
ONRR, Senior Project Manager

Mr. J. M. Sebroski
ONRR, Project Manager

Mr. V. R. Autry
DHEC