



PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

G/Gmax and Material Damping
Curves for Soil Layer 1

FIGURE 2.5.2-77

Rev 0