

AUDIT REPORT

REQUEST FOR RISK-INFORMED SOLUTION TO GSI-191

SOUTH TEXAS PROJECT NUCLEAR OPERATING COMPANY

SOUTH TEXAS PROJECT UNITS 1 AND 2

APRIL 2, 2015, CONTAINMENT WALKDOWN PICTURES



Insulation on Main Steam Line



Weld Location #3 on Hot Leg and #2 on Surge Line





Weld Location #3 on Hot Leg and # 2 on the Surge Line



Piping Near Weld Location #2 on Pressurizer Surge Line near Hot Leg





Piping Near Weld Location #2 on Pressurizer Surge Line near Hot Leg



Piping Near Weld Location #1 on Pressurizer Surge Line





Grating in the floor of containment near observed weld locations





Grating in the floor of containment



TSP baskets





TSP baskets





A bay of Recirculation Sump Strainers




Recirculation Sump Strainers






A bay of Recirculation Sump Strainers





End of a Recirculation Sump Strainer





Recirculation Sump Strainers up close



Containment spray ring headers at the top of containment





Storage Rack



Storage Rack





Storage Rack