

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH August 1986
REVISED

DOCKET NO. 50-247
UNIT NAME TP Unit #2
DATE 9/8/86
COMPLETED BY K. Krieger
TELEPHONE (914) 526-5155

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
9	860802	F	9.03	A	3	86-027	CH	Pump xx B	22 MBFP Trip due to low auto stop oil Signal. Corrective action/install new oil tubing to increase oil supply.
N/A	860831	F	0	A	NA	N/A	RB	CRDRVE	Experienced turbine runback due to dropped Control Rod (E9).

1
F. Forced
S. Scheduled

2
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

3
Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Other (Explain)

4
Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LIR) File (NUREG-0161)

5
Exhibit I - Same Source

(1177)

B701070072 861015
PDR ADOCK 05000247
R PDR