

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 186

FILE: INCIDENT REPORT FILE

| | | | | | | | | |
|---|----------------|-----------|-------------------------|----------------------|------------|--|-----|-------|
| FROM: Duek Power Co. Charlotte, N.C. W.O. Parker, Jr. | | | DATE OF DOC 12-17-75 | DATE REC'D 1-9-76 | LTR XXX | TWX | RPT | OTHER |
| TO: N.C. Moseley | | | ORIG 1 Signed | CC 0 | OTHER | SENT AEC PDR XXX SENT LOCAL PDR XXX | | |
| CLASS | UNCLASS XXX | PROP INFO | INPUT | NO CYS REC'D 1 | | DOCKET NO: 50-287 | | |

DESCRIPTION: Letter Re. their ltr. of 11-13-75
Letter providing additional info. and associated
corrective action to Unusual Event Report # 75-10
concerning a weld failure.....

ENCLOSURES:

(1 Copy Received)

PLANT NAME: Oconee # 3

FOR ACTION/INFORMATION

SAB 1-14-76

| | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L) W/ Copies | SCHWENCER (L) W/ Copies | ZIEMANN (L) W/ Copies | REGAN (E) W/ Copies |
| CLARK (L) W/ Copies | STOLZ (L) W/ Copies | DICKER (E) W/ Copies | LEAR (L) W/ Copies |
| PARR (L) W/ Copies | VASSALLO (L) W/ Copies | KNIGHTON (E) W/ Copies | SPELS W/ Copies |
| KNIEL (L) W/ Copies | PURPLE (L) W/3 Copies | YOUNGBLOOD (E) W/ Copies | REID W/ Copies |

**DO NOT REMOVE
ACKNOWLEDGED**

INTERNAL DISTRIBUTION

| | | | | |
|--|--|--|---|--|
| <u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE | <u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER | DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS | <u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E) | <u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER |
|--|--|--|---|--|

EXTERNAL DISTRIBUTION

| | | |
|--------------------------------|--------------------------------|---|
| 1 - LOCAL PDR Walhalla, S.C. | 1 - NATIONAL LABS | 1 - PDR-SAN/LA/NY |
| 1 - TIC (ABERNATHY) (1)(2)(10) | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB |
| 1 - NSIC (BUCHANAN) | 1 - CONSULTANTS | 1 - G. ULRIKSON, ORNL |
| 1 - ASLB | NEWMARK/BLUME/AGBABIAN | 1 - AGMED (RUTH GUSSMAN) Rm B-127 GT |
| 1 - Newton Anderson | S. Sheppard | 1 - J. D. RUNKLES, Rm E-201 GT |
| 1 - ACRS SENT TO LIC ASST | | |
| ** SEND ONLY TEN DAY REPORTS | | |

DUKE POWER COMPANY

POWER BUILDING


422 SOUTH CHURCH STREET, CHARLOTTE, N.C. 28202

Regulatory

File Cy.

December 17, 1975

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION



TELEPHONE: AREA 704
373-4083

Mr. Norman C. Moseley, Director
U. S. Nuclear Regulatory Commission
Suite 818
230 Peachtree Street, Northwest
Atlanta, Georgia 30303

Re: Oconee Unit 3
Docket No. 50-287



Dear Mr. Moseley:

My letter of November 13, 1975, transmitted Unusual Event Report UE-287/75-10, concerning a weld failure on a sample line from the 3A Low Pressure Injection System Cooler. The following provides additional information relating to this incident and associated corrective action.

The Corrective Action Section of UE-287/75-10 specified that representative welds in each Oconee unit would be dye penetrant tested to determine deleterious effects which may have been caused by vibration in the LPI trains. The welds listed in Units 1 and 2 were determined to be acceptable. For Unit 3, nine welds were tested, including one in each plane that would be affected by vibration, and the welds were determined to be acceptable with one exception. This weld had previously failed (refer to Abnormal Occurrence Report AO-287/74-6) and was on the same 3/4" sample line as the weld failure addressed by UE-287/75-10. Subsequently, this weld, and its adjacent line and valve, into which the crack extended, were replaced.

Very truly yours,

W.O. Parker, Jr.
William O. Parker, Jr.

EDB:ge

cc: Mr. Benard C. Rusche

DEC 18 10 21 AM '75

RECORDS SECTION
FBI
ATLANTA, GA

TO : SAC, NEW YORK
FROM : SAC, ATLANTA
SUBJECT: [Illegible]

[The following text is extremely faint and largely illegible due to the quality of the scan. It appears to be a multi-paragraph memorandum or letter.]