



Duke Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report

Primary and Orthogonal Fracture Pattern
 Local Avon Park Formation Outcrops
 FIGURE 2.5.4.1-202