

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Consulting Cardiologists, P.C.
85 Seymour Street, Suite 719
Hartford, Connecticut 06106

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region I, 2100 Renaissance Blvd, Suite 100
King of Prussia, Pennsylvania 19406-2713

REPORT NUMBER(S) 2016-001

3. DOCKET NUMBER(S)

030-30786

4. LICENSE NUMBER(S)

06-28274-01

5. DATE(S) OF INSPECTION

March 21, 2016, exit on April 25, 2016

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

- ☒ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)




10 CFR 35.60(b) requires, in part, that the licensee shall calibrate the instrumentation used to measure the activity of unsealed byproduct material in accordance with nationally recognized standards or the manufacturer's instructions.

Contrary to the above, on September 8, 2014, Consulting Cardiologists, P.C. did not calibrate instrumentation used to measure the activity of unsealed byproduct material at its new Glastonbury location in accordance with nationally recognized standards or the manufacturer's instructions. Specifically, the dose calibrator was not calibrated for geometric independence until March 22, 2016, rather than at its reinstallation at the new Glastonbury location on September 8, 2014, as set forth in the manufacturer's instructions.

This is a Severity Level IV violation (Enforcement Policy Example 6.3.d.3.). Corrective actions included performing the test for geometric independence on March 22, 2016, and retraining staff on dose calibrator testing requirements.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Jeffrey Walden		4-28-16
NRC INSPECTOR	Janice Nguyen		4-25-16
BRANCH CHIEF	James P. Dwyer		5/10/16

SUNSI Review Completed By: / RA / Janice Nguyen



Public



Non-Sensitive