



U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

DCS-NRC-000428
14 June 2016


Subject: Docket Number 070-03098
CB&I AREVA MOX Services
Mixed Oxide Fuel Fabrication Facility
Interim Report Notification: Vigor / Oregon Iron Works

This letter provides an interim report in accordance with §21.21 concerning an evaluation being performed by CB&I AREVA MOX Services, LLC (MOX Services) regarding a nonconformance identified at the Mixed Oxide Fuel Fabrication Facility. The nonconformance being evaluated pertains to inadequate vendor documentation of far vision acuity certifications for NDE personnel in accordance with American Welding Society (AWS) D1.6. These NDE personnel performed quality examinations on 28 PML gloveboxes manufactured for MOX Services.

Evaluation of reportability in accordance with §21.21 is not able to be completed within the evaluation period. Additional time is required to collect and evaluate the information pertaining to the identified nonconformance and to complete the evaluation. It is currently expected that the evaluation of this condition will be completed by 15 September 2016.

If you have any questions, please feel free to contact me at (803) 442-6485 or our Licensing and Nuclear Safety Manager, Dealis Gwyn, at (803) 819-2780.

Sincerely,



David Del Vecchio
President and Project Manager

Document Control Desk
U.S. Nuclear Regulatory Commission
DCS-NRC-000428
14 June 2016
Page 2 of 2

Enclosure:

Interim Report Notification Information per §21.21

cc:

Scott Cannon, NNSA/SRS
David Faubert, NNSA/SRS
William Gloersen, USNRC/RII
Mark Gober, MOX Services
Dealis Gwyn, MOX Services
Catherine Haney, USNRC/RII
Chip Hicks, MOX Services
Chad Huffman, USNRC/SRS
Dennis Ivey, MOX Services
Rebecca Nease, USNRC/RII
Gilles Rousseau, MOX Services
Donald Silverman, ML&B
David Tiktinsky, USNRC/HQ
Paul Whittingham, MOX Services
Bryan Wilkes, MOX Services
Lauren Wylie, MOX Services
Doug Yates, MOX Services
MOX Project Management Office Document Control Administrator (moxpmodca@srs.gov)
EDMS: Corresp\\Outgoing\\NRC\\2016 NRC

Enclosure

Interim Report Notification Information per §21.21

Interim Report Notification Information per §21.21

- (i) Name and address of the individual or individuals informing the Commission.

David Del Vecchio
President and Project Manager
CB&I AREVA MOX Services
Savannah River Site
P.O. Box 7097
Aiken, SC 29804-7097

- (ii) Identification of the facility, the activity, or the basic component supplied for such facility which fails to comply or contains a defect.

The Mixed Oxide Fuel Fabrication Facility is evaluating a nonconforming condition associated with inadequate vendor documentation of far vision acuity certifications for vendor NDE personnel in accordance with American Welding Society (AWS) D1.6 during fabrication of 28 PML gloveboxes. No basic components have been determined to contain a defect.

- (iii) Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.

No basic components have been determined to contain a defect. This is an interim report. The PML gloveboxes were supplied to MOX Services as a basic component by Vigor / Oregon Iron Works, 9700 S. E. Lawnfield Road, Clackamas, Oregon 97015.

- (iv) Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.

No basic components have been determined to contain a defect. This is an interim report. MOX Services is evaluating inadequate vendor documentation of far vision acuity certifications during fabrication of 28 PML gloveboxes.

- (v) The date on which the information of such defect or failure to comply was obtained.

Information related to the inadequate vendor documentation of far vision acuity certifications was documented by MOX Services on April 18, 2016.

- (vi) In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, being supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part.

MOX Services does not possess information as to whether other facilities have been supplied a similar basic component by Vigor / Oregon Iron Works.

- (vii) The corrective action, which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.

No basic components have been determined to contain a defect. This is an interim report. MOX Services engineering anticipates completion of our Part 21 reportability evaluation by 15 September 2016.

- (viii) Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.

None at this time.

- (ix) In the case of an early site permit, the entities to whom an early site permit was transferred.

Not applicable.