



U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

DCS-NRC-000434  
13 October 2016

Subject:       Docket Number 070-03098  
                  CB&I AREVA MOX Services  
                  Mixed Oxide Fuel Fabrication Facility  
                  Interim Report Notification: Vigor / Oregon Iron Works

This letter provides an interim report in accordance with §21.21 concerning an evaluation being performed by CB&I AREVA MOX Services, LLC (MOX Services) regarding a nonconformance identified at the Mixed Oxide Fuel Fabrication Facility. The nonconformance being evaluated pertains to inadequate vendor documentation for ancillary structural equipment weld maps associated with a limited number of PML gloveboxes.

Evaluation of reportability in accordance with §21.21 is not able to be completed within the evaluation period. Additional time is required to collect and evaluate the information pertaining to the identified nonconformance and to complete the evaluation. It is currently expected that the evaluation of this condition will be completed by 30 June 2017.

If you have any questions, please feel free to contact me at (803) 442-6485 or our Licensing and Nuclear Safety Manager, Dealis Gwyn, at (803) 819-2780.

Sincerely,



David Del Vecchio  
President and Project Manager

Document Control Desk  
U.S. Nuclear Regulatory Commission  
DCS-NRC-000434  
13 October 2016  
Page 2 of 2

Enclosure:

Interim Report Notification Information per §21.21

cc:

Scott Cannon, NNSA/SRS  
Michael Ernstes, USNRC/RII  
David Faubert, NNSA/SRS  
William Gloersen, USNRC/RII  
Mark Gober, MOX Services  
Dealis Gwyn, MOX Services  
Catherine Haney, USNRC/RII  
Chip Hicks, MOX Services  
Dennis Ivey, MOX Services  
Gilles Rousseau, MOX Services  
Donald Silverman, ML&B  
David Tiktinsky, USNRC/HQ  
Paul Whittingham, MOX Services  
Bryan Wilkes, MOX Services  
Lauren Wylie, MOX Services  
Doug Yates, MOX Services  
MOX Project Management Office Document Control Administrator (moxpmodca@srs.gov)  
EDMS: Corresp\\Outgoing\\NRC\\2016 NRC

**Enclosure**

**Interim Report Notification Information per §21.21**

**Interim Report Notification Information per §21.21**

- (i) Name and address of the individual or individuals informing the Commission.

David Del Vecchio  
President and Project Manager  
CB&I AREVA MOX Services  
Savannah River Site  
P.O. Box 7097  
Aiken, SC 29804-7097

- (ii) Identification of the facility, the activity, or the basic component supplied for such facility which fails to comply or contains a defect.

The Mixed Oxide Fuel Fabrication Facility is evaluating a nonconforming condition associated with inadequate vendor documentation for ancillary structural equipment weld maps associated with a limited number of PML gloveboxes. No basic components have been determined to contain a defect.

- (iii) Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.

No basic components have been determined to contain a defect. This is an interim report. The PML gloveboxes were supplied to MOX Services as a basic component by Vigor / Oregon Iron Works, 9700 S. E. Lawnfield Road, Clackamas, Oregon 97015.

- (iv) Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.

No basic components have been determined to contain a defect. This is an interim report. MOX Services is evaluating inadequate vendor documentation for ancillary structural equipment weld maps associated with a limited number of PML gloveboxes.

- (v) The date on which the information of such defect or failure to comply was obtained.

Information related to the inadequate vendor documentation of weld maps was documented by MOX Services on 18 August 2016.

- (vi) In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, being supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part.

MOX Services does not possess information as to whether other facilities have been supplied a similar basic component by Vigor / Oregon Iron Works.

- (vii) The corrective action, which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.

No basic components have been determined to contain a defect. This is an interim report. MOX Services engineering anticipates completion of our Part 21 reportability evaluation by 30 June 2017.

- (viii) Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.

None at this time.

- (ix) In the case of an early site permit, the entities to whom an early site permit was transferred.

Not applicable.