



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

July 23, 1979

Mr. Boyce H. Grier, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

REGULATORY DOCKET FILE COPY

Subject: LER 79-013/01T-0, Cracking in Feedwater System Piping found
during response to IE Bulletin 79-13
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Grier:

In accordance with Technical Specifications, Article 6.9.2.a(9) performance of structures, systems or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specification bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition, the attached report of Licensee Event Report LER 79-013/01T-0 is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.

L. D. White, Jr.

Attachment

cc: Mr. Victor Stello, Jr. (40)
Mr. Norman R. Haller (3)

7907260594

*A002
5/11*



1

100

6-10-51