

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:7908010365      DOC.DATE: 79/07/20      NOTARIZED: NO      DOCKET #  
FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe      05000397  
AUTH.NAME      AUTHOR AFFILIATION  
RENBERGER,D.L.      Washington Public Power Supply System  
RECIP.NAME      RECIPIENT AFFILIATION  
ENGELKEN,R.H.      Region 5, San Francisco, Office of the Director

SUBJECT: Forwards reportable deficiency re cable tray hangers from  
Quality Class II Structural Steel.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1  
TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: PM - 2 CYS All MATL


	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
ACTION:	14	PM M LYNCH	1	1	15	BC LWR 4	1	1
	20	LA LWR 4	1	1	21	ADVASSALLO	1	1
INTERNAL:	01	REG FILE	1	1	02	NRC PDR	1	1
	05	I&E	2	2	07	EDO & STAFF	1	1
	08	MPA	1	1	09	DEPY DIR DPM	1	1
	10	GAB	1	1	11	STANDRDS DEV	1	1
	12	JORDAN, E/IE	1	1	13	FIELD COOR/IE	1	1
	16	AD FOR ENGR	1	1	17	AD PLANT SYS	1	1
	17	AD REAC SFTY	1	1	19	AD SYS/PROJ	1	1
	22	DIR DPM	1	1	23	OELD	1	1
		AD/SITE TECH	1	1		DIRECTOR DSE	1	1
		GEOSCIENCES BR	1	1		STRUCT ANLYS BR	1	1
EXTERNAL:	03	LPDR	1	1	04	NSIC	1	1
	24	ACRS	16	16				

**AUG 3 1979**

TOTAL NUMBER OF COPIES REQUIRED: LTTR

44 44  
4/3 ENCL 4/3





Washington Public Power Supply System  
A JOINT OPERATING AGENCY

P. O. Box 968 3000 GEO. WASHINGTON WAY RICHLAND, WASHINGTON 99352 PHONE (509) 946-9681

July 20, 1979  
GU2-79-130

Nuclear Regulatory Commission  
Region V  
Office of Inspection and Enforcement  
Suite 202, Walnut Creek Plaza  
1900 N. California Boulevard  
Walnut Creek, California 93496

**REGULATORY DOCKET FILE COPY**

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2.  
DOCKET NUMBER 50-397, CPPR-93  
REPORTABLE DEFICIENCY - 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on June 21, 1979, of a reportable condition involving a possible failure of Quality Class I Tray Supports supported from Quality Class II Structural Steel.

Attached is our report of this deficiency.

Please contact us if you have additional questions.

Very truly yours,

*D. L. Renberger*

D. L. RENBERGER  
Assistant Director  
Technology

DLR/RPS/ln

Attachment: As stated

cc: JJ Verderber - B&R, w/att  
JJ Byrnes - B&R, w/att  
C Bryant - BPA, w/att  
JG Davis, Director, NRC, Washington, D.C., w/att  
WNP-2 Files, w/att

7908010365

3019  
5-1/1