


Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968 3000 GEO. WASHINGTON WAY RICHLAND, WASHINGTON 99352 PHONE (509) 946-9681

August 7, 1979
G02-79-138

Nuclear Regulatory Commission
Region V
Office of Inspection and Enforcement
Suite 202, Walnut Creek Plaza
1900 N. California Boulevard
Walnut Creek, California 94596



Attention: Mr. R. H. Engelken, Director
Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397, CPPR-93
REPORTABLE DEFICIENCY - 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on July 16, 1979, of a reportable condition involving the improper installation of anchor bolts by the Waldinger Corporation.

Attached is our report of this deficiency.

Please contact us if you have additional questions.

Very truly yours,

D. L. Renberger

D. L. RENBERGER
Assistant Director
Technology

DLR/RPS/ln

Attachment: As stated

cc: JJ Verderber - B&R, w/att
JJ Byrnes - B&R, w/att
C Bryant - BPA, w/att
JG Davis, Director, NRC, Washington, D.C., w/att
WNP-2 Files, w/att

79091 00 286

79-105