


Central File

Washington Public Power Supply System
A JOINT OPERATING AGENCY



P. O. Box 968

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

March 10, 1981
G02-81-54

Docket No. 50-397
CPPR-93

Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Gentlemen:

Subject: WPPSS NUCLEAR PROJECT NO. 2
NRC Inspection, June 3 - July 25, 1980
Report No. 50-397/80-08

- Reference: 1) Letter, R. H. Engelken to R. L. Ferguson,
dated August 15, 1980.
- 2) Letter, D. L. Renberger to R. H. Engelken,
dated September 19, 1980.

Washington Public Power Supply System (WPPSS) previously replied (Reference 2), to the Notice of Violation which was transmitted to us as Appendix A of Reference (1). Upon subsequent evaluation of that response, it was determined that Appendix A of Reference (2) requires clarification in several areas. These are:

1. Paragraph B.1. Actions To Correct Deficiency.

"...There are only eight equipment installation packages in the WBG Quality Assurance vault..."

We have found additional equipment packages in the WBG QA vault. All equipment packages are being dispositioned in accordance with our previous commitment.

8105150 342

Q

81-38

117

2. 3



10

117

2. Paragraph B.2. Actions To Prevent Recurrence.

"WBG will review Quality Assurance Procedure No. 15..."

The statement should have referenced Quality Assurance Procedure (QAP) No. 5 which is now QAP No. 360.

3.A.Paragraph B.4. Action To Correct Deficiency.

"Inspection Reports have been issued for both EDR-362 and RCC-457..."

B.Paragraph D.3. Actions To Correct Deficiency.

"...Inspection Reports have been written on the weld record packages for pipe spools LPCS-756-5.6, LPCS-756-19.21 and LPCS-2271-1."

C.Paragraph B.7. Actions To Correct Deficiency.

"...The 72 hour MT has now been performed and found acceptable..."

Review has shown that the Inspection Reports cited in Paragraphs B.4 and D.3 and that the 72 hour MT referenced in Paragraph B.7. were not completed as indicated by the contractor and subsequently reported by WPPSS in Reference (2). We are reviewing each of the contractors responses on action items committed to the NRC on a case by case basis to assure proper differentiation between actions already completed and those committed for action.

Please contact me if you have further questions in this regard.

Very truly yours,


R.G. MATLOCK
WNP-2 Program Director

RGM/JPT/see

cc: V. Stello, Director, NRC Office of Inspection and Enforcement, DC
A. D. Toth, NRC Resident Site Inspector
R. E. Snaith, Burns and Roe, NY
J. J. Verderber, Burns and Roe, NY
R. C. Root, Burns and Roe, WNP-2 Site
W. S. Chin, Bonneville Power Administration - Site
WNP-2 Files

