

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9812090193      DOC.DATE: 98/12/03    NOTARIZED: NO      DOCKET #  
FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe    05000397  
AUTH.NAME                  AUTHOR AFFILIATION  
COLEMAN,D.W.                Washington Public Power Supply System  
RECIP.NAME                  RECIPIENT AFFILIATION  
                             Records Management Branch (Document Control Desk)

SUBJECT: Forwards WNP-2 feedwater nozzle insp rept for R-13 maint & refueling outage. Rept submitted pursuant to commitments made in response to NUREG-0619, "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking."

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4  
TITLE: OR Submittal: General Distribution

**NOTES:**

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD4-2 LA		1	1		PD4-2 PD		1	1
	POSLUSNY, C		1	1					
INTERNAL:	ACRS		1	1		FILE CENTER 01		1	1
	NRR/DE/ECGB/A		1	1		NRR/DE/EMCB		1	1
	NRR/DRCH/HICB		1	1		NRR/DSSA/SPLB		1	1
	NRR/DSSA/SRXB		1	1		NRR/SPSB JUNG, I		1	1
	NUDOCS-ABSTRACT		1	1		OGC/HDS3		1	0
EXTERNAL:	NOAC		1	1		NRC PDR		1	1

**MICROFILMED**

**NOTE TO ALL "RIDS" RECIPIENTS:**

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

**TOTAL NUMBER OF COPIES REQUIRED: LTTR 15 ENCL 14**

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • Richland, Washington 99352-0968

December 3, 1998  
GO2-98-203

Docket No. 50-397

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

Gentlemen:

Subject: WNP-2, OPERATING LICENSE NPF-21  
FEEDWATER NOZZLE INSPECTION REPORT  
R-13 MAINTENANCE AND REFUELING OUTAGE

Reference: Letter GO2-95-268, dated December 8, 1995, JV Parrish (SS) to NRC,  
"WNP-2 Feedwater Nozzle Inspection Report"

The WNP-2 Feedwater Nozzle Inspection Report for the R-13 Maintenance and Refueling Outage is attached. This report is submitted pursuant to commitments made in response to NUREG-0619, "BWR Feedwater Nozzle and Control Rod Drive Return Line Nozzle Cracking."

Should you have any questions or desire additional information pertaining to this report, please call me or PJ Inserra at (509) 377-4147.

Respectfully,

*D. W. Coleman*

DW Coleman  
Manager, Regulatory Affairs  
Mail Drop PE20

Attachment

cc: EW Merschoff - NRC RIV  
GA Pick - NRC RIV  
C Poslusny, Jr. - NRR

390008

NRC Sr. Resident Inspector - 927N  
DL Williams - BPA/1399  
PD Robinson - Winston & Strawn

9812070193 981203  
PDR ADDCK 05000397  
G PDR



11.  
9001

# WNP-2 FEEDWATER NOZZLE INSPECTION REPORT R-13 MAINTENANCE AND REFUELING OUTAGE

Attachment

Page 1 of 3

## I. Introduction

This report is submitted pursuant to the Supply System response to NUREG-0619, where we committed to perform ultrasonic examinations of at least one of the six feedwater nozzle inner radii, bore and safe-end regions from the reactor outside diameter each refueling outage.

The report covers the period from June 30, 1997 to June 12, 1998 and includes reactor vessel feedwater nozzle inspections performed during the WNP-2 R-13 Maintenance and Refueling Outage (Spring 1998).

As with all previous examinations, no unacceptable indications were found during this inspection period.

## II. Report Details

These report details are formatted in accordance with the reporting guidance of Section 4.4.3.1(2) of NUREG-0619.

- (a) Number of startup/shutdown cycles since the previous inspection and total number of cycles.

There were two startup/shutdown cycles from the date of the previous feedwater nozzle inner radius examination (Spring 1997) to when the plant was shutdown in April 1998 for the R-13 Maintenance and Refueling Outage.

The total number of reactor feedwater thermal cycles, due to startups and shutdowns since initial heatup in April 1984, is 63.

- (b) Summary of methods used and results of previous inspections.

The Supply System has developed an angle beam shear wave technique for the WNP-2 feedwater nozzle design. The technique was qualified on the WNP-2 feedwater mock-up, which is a feedwater nozzle from the terminated Douglas Point Unit 1 reactor vessel. The inner radius, Zone 1, of the nozzle is scanned using a 70-degree angle transducer. The inner radius, Zone 2, and bore region, Zone 3, are scanned using a 25-degree angle transducer.

# WNP-2 FEEDWATER NOZZLE INSPECTION REPORT R-13 MAINTENANCE AND REFUELING OUTAGE

Attachment  
Page 2 of 3

The ultrasonic testing (UT) procedure used for the examinations is Supply System NDE&I Instruction QCI 6-4 "Ultrasonic Examination of Feedwater Nozzle Inner Radii." A copy of QCI 6-4 was included in the R10 feedwater nozzle inspection report (see Reference). Any changes to this procedure that affect UT scanning techniques are verified on the feedwater nozzle mock-up. No changes to this procedure have been made since the R10 submittal.

Calibration data for reactor feedwater nozzle inner radius examinations have also been predetermined using the WNP-2 feedwater nozzle mock-up. This allows the examiner to use the reactor vessel calibration block representing the shell course containing the feedwater nozzle for calibration.

Indications that exceed 25 percent full-screen-height are recorded. Indications that exceed 50 percent full-screen-height are evaluated.

No unacceptable indications were detected from these feedwater nozzle inner radius examinations.

- (c) Changes in feedwater system or operating procedures that will affect feedwater flow or temperature.

There were no changes to the system or method of operation that could potentially increase the tendency for nozzle cracking.

- (d) Inspection results.

During the R-13 Maintenance and Refueling Outage, ultrasonic examination of one reactor feedwater nozzle inner radius, bore and nozzle-to-safe-end weld at azimuth 90 from the vessel outside diameter was performed.

The examinations were performed by Supply System and General Electric examiners. These examiners were certified to either Level II or Level III UT.

No indications were detected that met the threshold for recording or evaluation.

- (e) Leakage monitoring.

We do not have on-line leakage monitoring for the reactor feedwater sparger.

WNP-2 FEEDWATER NOZZLE INSPECTION REPORT R-14 MAINTENANCE AND  
REFUELING OUTAGE

Attachment

Page 3 of 3

- (f) Information regarding all UT crack-like indications and any subsequent liquid penetrant information.

No crack-like indications were observed.

III. Next Scheduled Examination

The next examination is scheduled for the R-14 Maintenance and Refueling Outage (Fall, 1999).