

DOCKET NO. 50-397

UNIT NAME WNP-2

DATE 9/1/90

COMPLETED BY LB Hutchison

TELEPHONE (509) 377-2486

UNIT SHUTDOWNS / REDUCTIONSREPORT PERIOD Aug. 1990
month, year

NO.	DATE	TYPE	HOURS	REASON	METHOD	LER NUMBER	SYSTEM	COMPONENT	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
90-04P	8/14/90	S	0	B	5	-	HA	PIPEXX	Reduced load to permit repair of a leaking manway cover on turbine crossunder steam piping.

NOTE: THIS IS AN ADDENDUM TO THE AUGUST 1990 REPORT WHICH WAS PREVIOUSLY TRANSMITTED.SUMMARY

WNP-2 returned to service from refueling outage. Subsequently, a scheduled outage for testing and one power reduction occurred.

TYPE	REASON	METHOD	SYSTEM & COMPONENT
F-Forced	A-Equip Failure	F-Admin	Exhibit F & H
S-Sched	B-Maint or Test	G-Oper Error	Instructions for
	C-Refueling	H-Other	Preparation of
	D-Regulatory Restriction		Data Entry Sheet
	E-Operator Training		Licensee Event Report
	& License Examination		(LER) File (NUREG-0161)
		1-Manual	
		2-Manual Scram	
		3-Auto Scram	
		4-Continued	
		5-Reduced Load	
		9-Other	

9010160287 901008
PDR ADDCK 05000397
PDC

1990