

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9603220204 DOC. DATE: 96/03/14 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Power 05000397
 AUTH. NAME: PARRISH, J.V. AUTHOR AFFILIATION: Washington Public Power Supply System
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Submits correction of info supplied in response to GL 94-08,
 "Intergranular Stress Corrosion Cracking of Core Shrouds."

DISTRIBUTION CODE: A018D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: GL 94-03 Intergranular Stress Corrosion Cracking of Core Shrouds in B

NOTES:

	RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL	
	CLIFFORD, J		1	1	
INTERNAL: FILE CENTER 01			1	1	
	NRR/DE/EMEB		1	1	
	NRR/DSSA/SRXB		1	1	
EXTERNAL: NRC PDR			1	1	

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWEN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 9 ENCL 0

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352-0968 • (509) 372-5000

March 14, 1996
GO2-96-055

Docket No. 50 -397

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington D.C. 20555

Gentlemen:


Subject: WNP-2, OPERATING LICENSE NPF-21
CORRECTION OF INFORMATION SUPPLIED IN RESPONSE TO
GENERIC LETTER 94-03, INTERGRANULAR STRESS CORROSION
CRACKING OF CORE SHROUDS, RE: CRACK PROPAGATION

- References:
- 1) E-mail dated February 21, 1996, DA Swank (SS) to JW Clifford (NRC), "Core Shroud"
 - 2) Letter dated February 20, 1996, JV Parrish (SS) to US Nuclear Regulatory Commission, "Supplement To Response To Generic Letter 94-03"
 - 3) Letter dated August 24, 1994, JV Parrish (SS) to US Nuclear Regulatory Commission, "Response To Generic Letter 94-03, 'Intergranular Stress Corrosion Cracking of Core Shrouds'"

Confirming Reference 1, an error was identified in Reference 2. In the third paragraph, the sentence beginning with "The UT inspection...." should be corrected to read "The UT inspection performed during the R-9 outage of 35% of the H3 and 18% of the H4 weld ligaments showed no indication of weld cracking." This correction makes this detail in Reference 2 consistent with Reference 3.

Should you have any questions or desire additional information regarding this matter, please call me or Mr. Dave Swank at (509)-377-4563.

Sincerely,



J.V. Parrish (Mail Drop 1023)
Chief Executive Officer

cc: LJ Callan - NRC RIV
KE Perkins, Jr. - NRC RIV, WCO
NS Reynolds - Winston & Strawn

JW Clifford - NRC
DL Williams - BPA/399
NRC Resident Inspector - 927N

AD1810

000000

000000