

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8604180177 DOC. DATE: 86/04/16 NOTARIZED: NO DOCKET #
 FACIL: STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529
 AUTH. NAME AUTHOR AFFILIATION
 VAN BRUNT, E. E. Arizona Nuclear Power Project (formerly Arizona Public Serv
 RECIP. NAME RECIPIENT AFFILIATION
 KNIGHTON, G. W. PWR Project Directorate 7

SUBJECT: Forwards Rev 2 to rept re single pipe support failure in
 Unit 1 containment. Eccentric loading of support is
 significant Factor. Three supports requiring design Mods
 identified. Necessary Mods will be completed before M 2.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1711
 TITLE: DR Submittal: General Distribution

NOTES: Standardized plant.

05000529

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	PWR-B ADTS		1 0		PWR-B EB		1 1
	PWR-B PEICSB		2 2		PWR-B FOB		1 1
	PWR-B PD7 PD 01		5 5		LICITRA, E		1 1
	PWR-B PEICSB		1 1		PWR-B RSB		1 1
INTERNAL:	ACRS	09	6 6		ADM/LFMB		1 0
	ELD/HDS3		1 0		NRR/DHET/TSCB		1 1
	NRR/ORAS		1 0		<u>REG FILE</u>	04	1 1
	RGN5		1 1				
EXTERNAL:	24X		1 1		EG&G BRUSKE, S		1 1
	LPDR	03	1 1		NRC PDR	02	1 1
	NSIC	05	1 1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 30 ENCL 26



[The page contains extremely faint, illegible text arranged in several columns. The text appears to be a formal document or report, possibly containing dates, names, and descriptive paragraphs. Due to the low contrast and quality of the scan, the specific content cannot be transcribed.]



Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

April 16, 1986
ANPP-36154-EEVB/RAB/98.05

Director of Nuclear Reactor Regulation
Attention: Mr. George W. Knighton, Project Director
PWR Project Directorate #7
Division of Pressurized Water Reactor Licensing - B
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Palo Verde Nuclear Generating Station
Unit 2
Docket No. STN 50-529 (License NPF-46)
Revision to Report on Pipe Support Failure
File: 86-073-419, P.3.04.1

Reference: Letter ANPP-36021 - EEVB/RAB/98.05 dated April 9, 1986

Dear Sir:

The referenced letter transmitted our report (Rev. 1) concerning the single pipe support failure in the Unit 1 containment. We have continued to evaluate this incident, and we have determined that eccentric loading of the support was also a significant factor in the cause of the failure. The updated report (Rev. 2) is attached to this letter.

Evaluation of eccentric loading resulted in the identification of three supports requiring design modifications. Necessary modifications will be completed prior to entering MODE 2.

Very truly yours,

E. E. Van Brunt, Jr.
Executive Vice President
Project Director

EEVB/RAB/dlm
Attachment

cc: E. A. Licitra (all w/a)
R. P. Zimmerman
A. C. Gehr
J. B. Martin

8604180177 860416
PDR ADDCK 05000529
PDR

1001
11

