

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8604220094 DDC DATE: 86/04/18 NOTARIZED: NO DOCKET #  
 FACIL: STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528  
 STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529  
 AUTH. NAME AUTHDR AFFILIATION  
 VAN BRUNT, E. E. Arizona Nuclear Power Project (formerly Arizona Public Serv  
 RECIP. NAME RECIPIENT AFFILIATION  
 KNIGHTON, G. W. PWR Project Directorate 7

SUBJECT: Forwards Rev 3 to, "Weld Failure on Palo Verde Nuclear  
 Generating Station Unit 1 Pipe Support Structure." Update  
 identifies addl supports requiring mod.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 17 13  
 TITLE: OR Submittal: General Distribution

NOTES: Standardized plant.  
 Standardized plant.

05000528  
 05000529

RECIPIENT			COPIES		RECIPIENT			COPIES	
ID CODE/NAME			LTTR	ENCL	ID CODE/NAME			LTTR	ENCL
PWR-B	ADTS		1	0	PWR-B	EB		1	1
PWR-B	PEICSB		2	2	PWR-B	FOB		1	1
PWR-B	PD7 PD 01		5	5	LICITRA, E			1	1
PWR-B	PEICSB		1	1	PWR-B	RSB		1	1
INTERNAL:	ACRS	09	6	6	ADM/LFMB			1	0
	ELD/HDS3		1	0	NRR/DHET/TSCB			1	1
	NRR/ORAS		1	0	<u>REG FILE</u>	04		1	1
	RGN5		1	1					
EXTERNAL:	24X		1	1	EG&G BRUSKE, S			1	1
	LPDR	03	1	1	NRC PDR	02		1	1
	NSIC	05	1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTTR 30 ENCL 26





## Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

April 18, 1986  
ANPP-36289-EEVB/JRP/98.05

Director of Nuclear Reactor Regulation  
Attention: Mr. George W. Knighton, Project Director  
PWR Project Directorate #7  
Division of Pressurized Water Reactor Licensing - B  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Subject: Palo Verde Nuclear Generating Station  
Unit 2  
Docket No. STN 50-529 (License NPF-46)  
Revision to Report on Pipe Support Failure  
File: 86-073-419, P.3.04.1

Reference: (A) Letter ANPP-36154 - EEVB/RAB/98.05 dated April 16, 1986

Dear Sir:

Attached for your information is our updated report (Revision 3) regarding the evaluation of a Unit 1 pipe support failure. This update identifies the additional supports requiring modification as the result of the completion of our review, clarifies the information provided in the previous report, and provides further information to be considered in the determination of the root cause.

Very truly yours,

E. E. Van Brunt, Jr.  
Executive Vice President  
Project Director

EEVB/RAB/dlm  
Attachment

cc: E. A. Licitra (all w/a)  
R. P. Zimmerman  
A. C. Gehr  
J. B. Martin

8604220094 860418  
PDR ADDCK 05000529  
P PDR

