

# PRIORITY 1

(ACCELERATED RIDS PROCESSING)

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9503070284      DOC.DATE: 95/02/28      NOTARIZED: NO      DOCKET #  
 FACIL:STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529  
 AUTH.NAME      AUTHOR AFFILIATION  
 STEWART,W.L.      Arizona Public Service Co. (formerly Arizona Nuclear Power  
 RECIP.NAME      RECIPIENT AFFILIATION  
                  Document Control Branch (Document Control Desk) *see report*

SUBJECT: Forwards "PVNGS Unit 2 SG Eddy Current Exam U2M5 Midcycle Outage." Generators inspected in Jan 1994, using eddy current testing technology comprised of both bobbin coil probe & motorized rotating pancake coil probe.

DISTRIBUTION CODE: A001D      COPIES RECEIVED:LTTR 1 ENCL 1      SIZE: 1+200  
 TITLE: OR Submittal: General Distribution

NOTES:Standardized plant.

05000529

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD4-2 LA	1 1	PD4-2 PD	1 1
	HOLIAN, B	1 1	TRAN, L	1 1
INTERNAL:	ACRS	6 6	<del>FILE CENTER</del> 01	1 1
	NRR/DRCH/HICB	1 1	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	NUDOCS-ABSTRACT	1 1
	OGC/HDS2	1 0		
EXTERNAL:	NOAC	1 1	NRC PDR	1 1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 17



Arizona Public Service Company  
P.O. BOX 53999 • PHOENIX, ARIZONA 85072-3999

WILLIAM L. STEWART  
EXECUTIVE VICE PRESIDENT  
NUCLEAR

February 28, 1995  
001-00707-WLS

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-37  
Washington, DC 20555-0001

Reference: Letter 102-02852, dated March 8, 1994, from W.F. Conway, Executive Vice President Nuclear, APS, to USNRC

Dear Sirs:


Subject: Palo Verde Nuclear Generating Station (PVNGS)  
Unit 2  
Docket No. STN 50-529  
Steam Generator Eddy Current Examination- Midcycle Outage (U2M5)  
File: 95-056-026

In accordance with Technical Specification 4.4.4.5b, attached please find the Unit 2 Steam Generator Eddy Current Examination Report-Midcycle Outage (U2M5). The Unit 2 steam generators were inspected in January 1994, using eddy current testing technology comprised of both bobbin coil probe and motorized rotating pancake coil probe. The inspection identified a total of 330 tubes as having axial indications, 22 in steam generator 2-1 and 308 in steam generator 2-2. Four tubes having circumferential indications were also identified in steam generator 2-2 at the hotleg tubesheet. This information was previously transmitted to the staff by the referenced letter.

Should you have any questions, please call Scott A. Bauer at (602) 393-5978.

Sincerely,

WLS/SAB/JRP/rv  
Attachment



cc: L. J. Callan  
K. E. Perkins  
K. E. Johnston  
B. E. Holian  
I. Barnes

070133

9503070284 950228  
PDR ADOCK 05000529  
Q. PDR

ADD1

