

5

DOCKET #
05000530

C
A
T
J
E
G
O
R
Y
1
D
O
C
U
M
E
N
T

$$\underline{1 + 4}$$

05000530^E

G
O
R
Y
1
D
O
C
U
M
E
N
T

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

A04



Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01030-GRO/DGM/RAS
September 14, 1998

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 3
Docket No. STN 50-530
License No. NPF-74
Licensee Event Report 98-002-00

Attached please find Licensee Event Report (LER) 98-002-00 prepared and submitted pursuant to 10 CFR 50.73. This LER describes the discovery and correction of a cross-wired power supply receptacle for the "B" train Hydrogen Recombiner. The power supply receptacle was configured such that had it been utilized, the blower motor of the supplied Hydrogen Recombiner would have rotated in the reverse direction.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have questions regarding this submittal, please contact Daniel G. Marks, Section Leader, Regulatory Affairs, at (602) 393-6492.

Sincerely,

GRO/DGM/RAS/rjh

Attachment

cc: E. W. Merschoff (all with attachment)
J. H. Moorman
M. B. Fields
INPO Records Center

9809230022 980914
PDR ADDCK 05000530
S PDR



1
2
3