

10/20/78

Donald H. Lanham
DSB - Philips 042

Don -

License report RO 78-054/03L-0 on
docket 50-315 was apparently not
included by the licensee in their
attached October 3, 1978 letter. You have
already put RO 78-053/03L-0 in the
system.

Please have your contractor enter
RO-78-054 into the system and
make the appropriate distributions
throughout the NRC. I got a copy
of the RO-78-054 from the
principal inspector of Region II.

If there are any questions, please
call me on 492. 77 35 or 36

RECEIVED OCT 21 1978 COPY

Thanks

LER 78-053 is under
78 10 11 0192

Paul E. Bobe
MPA/COEB

A002
5/11

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 9 9 0 7 7 8 8 1 0 0 3 7 8 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE IN MODE ONE, THE CONTAINMENT ATMOSPHERE GASEOUS AND PARTICULATE MONITORING
0 3 PUMP WAS DISCOVERED TO BE INOPERABLE. THE ACTION ITEMS IMPOSED BY T.S. TABLE
0 4 3.3-6 WERE OBSERVED WITH THE PUMP RETURNED TO SERVICE WITHIN EIGHT HOURS OF
0 5 EVENT DISCOVERY. SIMILAR OCCURRENCES INCLUDE: 050-315/75-039,050,062;
0 6 050-315/76-06,027,053; 050-315/77-036 and 050-316/78-03,036.
0 7
0 8

0 9 SYSTEM CODE B B 11 CAUSE CODE E 12 CAUSE SUBCODE H 13 COMPONENT CODE P U M P X X 14 COMP. SUBCODE H 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
17 LER/RO REPORT NUMBER 7 8 EVENT YEAR 7 8 SEQUENTIAL REPORT NO. 0 5 3 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0
ACTION TAKEN C 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NRPD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER C 5 2 1 1 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE FAILURE OF THE PUMP IS ATTRIBUTED TO NATURAL END OF LIFE. A REPLACEMENT
1 1 PUMP OF IMPROVED DESIGN WAS INSTALLED AND OPERABILITY VERIFIED PRIOR TO ITS
1 2 RETURN TO SERVICE. THE NEW PUMP HAS A LONGER OPERATION EXPECTANCY WHICH
1 3 SHOULD PRECLUDE FUTURE OCCURRENCES. NO ADDITIONAL ACTION IS PLANNED AT
1 4 THIS TIME.

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION SUPERVISOR OBSERVATION 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER T. P. Beilman

PHONE: 616-465-5901

NRC USE ONLY