

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7902080.173 DOC. DATE: 79/0.1/23 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH. NAME AUTHOR AFFILIATION
 SHALLER, D.V. Indiana & Michigan Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 KEPPLER, J.G. Region 3, Chicago, Office of the Director

SUBJECT: Forwards "Special Rept SI-1.1" re 780114 Safety injection
 actuation occurrence resulting from operator error. Major
 components & functions were reviewed & found to be in good
 order. W/2 previous repts having new rept numbers.

DISTRIBUTION CODE: A002S. COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7
 TITLE: INCIDENT REPORTS


NOTES: *I & E - 3 cys All Matl.*

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	05 BC DRB #1	4 4		
INTERNAL:	01 <u>REG FILE</u>	1 1	02 NRC PDR	1 1
	09 I&E	2 2	11 MPA	3 3
	14 TA/EDO	1 1	15 NOVAK/KNIEL	1 1
	16 EEB	1 1	17 AD FOR ENGR	1 1
	18 PLANT SYS BR	1 1	19 I&C SYS BR	1 1
	20 AD PLANT SYS	1 1	21 AD SYS/PROJ	1 1
	22 REAC SAFT BR	1 1	23 ENGR BR	1 1
	24 KREGER	1 1	25 PWR SYS BR	1 1
	26 AD/SITE ANAL	1 1	27 OPERA LIC BR	1 1
	28 ACIDENT ANLYS	1 1	E JORDAN/IE	1 1
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	29 ACRS	16 16		

FEB 9 1979
 1979

MA 4
 60

TOTAL NUMBER OF COPIES REQUIRED: LTTR 45 ENCL 45





INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

January 23, 1979

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315
Special Report: SI-11

Dear Mr. Keppler:

The purpose of this letter is to forward you the attached Special Reports as required by Appendix A Technical Specification 3.5.2 Emergency Core Cooling Subsystems.

Special Report SI-11 should have been submitted prior to April 14, 1978.

Our letter to you of November 7, 1978 also reported two instances of failure to submit a Special Report within 90 days. At that time we established a tickler system for Special Reports but did not attempt to backfit all internal reports to determine if any other reports had been missed. Resident Inspector Mr. K. R. Baker, in his review of internal reports, discovered that we had failed to submit the attached report.

We have now reviewed all internal reports and determined there are no other missing Special Reports required. This review also revealed we had submitted two Special Reports numbered SI-08. To correct this discrepancy, we are enclosing renumbered reports. SI-08 for the safety injection actuation which occurred on September 2, 1977 has been changed to SI-09. SI-09 for the safety injection actuation which occurred on September 4, 1977 has been renumbered SI-10.

Sincerely,

D. V. Shaller
Plant Manager

REGULATORY DOCKET FILE COPY

APR 23 1979

cc: J. E. Dolan
R. W. Jurgensen
R. F. Kroeger

R. J. Vollen BPI
K. R. Baker RO:III
R. C. Callen MPSC

P. W. Steketee, Esq.
R. Walsh, Esq.
M. H. Judkis

PNSRC
J. F. Stietzel
R. S. Keith

7902080173

13 1979

11-11-11

27-11-11