

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 3 0 3 7 9 8 0 3 2 8 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

DURING NORMAL OPERATION, MAIN TURBINE STOP VALVE "C" CLOSURE LIMIT SWITCH WAS

FOUND TO HAVE FAILED DURING A SURVEILLANCE TEST. THIS SWITCH PROVIDES A TRIP

SIGNAL AS LISTED IN T.S. TABLE 3.3-1 ITEM 18.b THIS SWITCH FAILED CONSERVATIVELY

IN THAT THE STOP VALVE CLOSURE INDICATION WAS RECEIVED. PREVIOUS OCCURRENCES

INCLUDE: 316/78-77-29.

09		SYSTEM CODE I A		11	CAUSE CODE X		12	CAUSE SUBCODE Z		13	COMPONENT CODE I N S T R U						14	COMP. SUBCODE S		15	VALVE SUBCODE Z		16					
17		LER/RO REPORT NUMBER		EVENT YEAR 7 9		21	22	SEQUENTIAL REPORT NO. 0 0 8		24	26	OCCURRENCE CODE 0 3		28	29	REPORT TYPE L		30	REVISION NO. 0		32							
ACTION TAKEN A		33	FUTURE ACTION Z		34	EFFECT ON PLANT Z		35	SHUTDOWN METHOD Z		36	HOURS 0 0 0 0		37	40	ATTACHMENT SUBMITTED Y		41	NPRD-4 FORM SUB. Y		42	PRIME COMP. SUPPLIER N		43	COMPONENT MANUFACTURER 0 0 0 7		44	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

THE ACTUAL CAUSE OF THIS FAILURE IS UNKNOWN, SINCE THIS TYPE OF LIMIT SWITCH IS A

POTTED SOLID STATE UNIT AND CANNOT BE DISASSEMBLED. THIS LIMIT SWITCH WAS

MANUFACTURED BY NAMCO CONTROLS, MODEL NUMBER EE 520-5. THIS WAS A NEW TYPE SWITCH,

INSTALLED DUE TO THE FAILURE OF A PREVIOUS TYPE. THE LIMIT SWITCH WAS REPLACED AND

RECONNECTED ON MARCH 9, WHEN THE VALVES WERE CYCLED. SEE SUPPLEMENT.

FACILITY STATUS							% POWER							OTHER STATUS							METHOD OF DISCOVERY							DISCOVERY DESCRIPTION						
E							088							NA							B							SURVEILLANCE TEST						
15							28							29							31							32						
ACTIVITY CONTENT RELEASED							OF RELEASE							AMOUNT OF ACTIVITY														LOCATION OF RELEASE						
16							Z							Z							NA							NA						
PERSONNEL EXPOSURES							NUMBER							TYPE							DESCRIPTION													
17							000							Z							NA													
PERSONNEL INJURIES							NUMBER							DESCRIPTION																				
18							000							40							NA							79040.30209						
LOSS OF OR DAMAGE TO FACILITY							TYPE							DESCRIPTION																				
19							Z							42							NA													
PUBLICITY ISSUED							DESCRIPTION																											
20							N							44							NA													
																												NRC USE ONLY						

NAME OF PREPARER J. L. Rischling

PHONE: 616-465-5901

SUPPLEMENT TO LER #79-008/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THIS ALLOWED FOR ALIGNMENT OF THE LIMIT SWITCH AND VERIFIED THAT
THE APPROPRIATE ALARM/TRIP SIGNAL FUNCTIONED PROPERLY.
NO FURTHER ACTION IS PLANNED AT THIS TIME

