



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

September 18, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following report/s are submitted:

RO 79-044/03L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
R.E. Masse RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
J.F. Stietzel
E.L. Townley
PNSRC
Dir., IE (30 copies)
Dir., MIPC (3 copies)

7909250358

SEP 26 1979

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

0 1 REPORT SOURCE 6 0 5 0 - 0 3 1 5 7 0 8 2 5 7 9 8 0 9 1 8 7 9 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING A ROUTINE INSPECTION, A CABLE PENETRATION IN THE FLOOR OF THE HOT

0 3 SHUTDOWN PANEL WAS FOUND TO HAVE THE FIRE BARRIER SEAL REMOVED WITHOUT A

0 4 CONTINUOUS FIRE WATCH STATIONED. THIS IS CONTRARY TO THE REQUIREMENTS OF

0 5 T.S. 3.7.10. A CONTINUOUS FIRE WATCH WAS IMMEDIATELY STATIONED.

0 6

0 7

0 8

0 9 SYSTEM CODE A B (11) CAUSE CODE A (12) CAUSE SUBCODE F (13) COMPONENT CODE X X X X X X X (14) COMP. SUBCODE Z (15) VALVE SUBCODE Z (16)

7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER 7 9 EVENT YEAR 7 9 SEQUENTIAL REPORT NO. 0 4 4 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

0 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 Z 25 Z 9 9 9 9 26

33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE SEAL MATERIAL HAD BEEN REMOVED BY CONTRACT PERSONNEL TO INSTALL

1 1 NEW CABLES FOR A DESIGN CHANGE. THE CONTRACTOR FAILED TO COMPLY WITH

1 2 APPROVED PLANT PROCEDURE. THE CONTRACTOR HAS BEEN INSTRUCTED TO INSTALL

1 3 TEMPORARY SEALS PRIOR TO CONCLUSION OF EACH DAY'S WORK. THIS WILL BE

1 4 MONITORED ON A ROUTINE BASIS.

1 5 FACILITY STATUS E (28) % POWER 1 0 0 (29) OTHER STATUS N/A (30) METHOD OF DISCOVERY L (31) N/A DISCOVERY DESCRIPTION (32)

7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION N/A (39)

7 8 9 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION N/A (41)

7 8 9 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION N/A (43)

7 8 9 10 80

2 0 PUBLICITY ISSUED N (44) DESCRIPTION N/A (45)

7 8 9 10 80

NRC USE ONLY

NAME OF PREPARER D. G. WIZNER

PHONE: 616 465-5901

YLL7/19/01