



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

October 1, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following report/s are submitted:

RO 79-045/03L-0.

Sincerely,

for D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
R.E. Masse RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

OCT 3 1979

7910090469

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC1 200-00000-00 341111 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CONT

01 REPORT SOURCE L 605000315 7083179 8100179 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

DURING A ROUTINE TOUR ON 8-31-79, ONE ICE CONDENSER INTERMEDIATE DECK

DOOR WAS FOUND TO BE FROZEN SHUT CONTRARY TO THE REQUIREMENTS OF T.S.

3.6.5.3. A SIMILAR SITUATION WAS DISCOVERED 9-17-79 WHEN SIX DOORS

WERE FOUND FROZEN. IN BOTH CASES, THE ICE WAS CHIPPED AWAY AND THE

DOORS WERE FREED. THIS EVENT DID NOT AFFECT PUBLIC HEALTH AND SAFETY.

A SIMILAR OCCURRENCE WAS REPORTED AS #79-036/03L-0.

09 SYSTEM CODE XX 11 CAUSE CODE C 12 CAUSE SUBCODE Z 13 COMPONENT CODE H T E X C H 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 79 21 22 23 SEQUENTIAL REPORT NO. 045 24 26 27 OCCURRENCE CODE 03 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0000 22 N 23 N 24 N 25 W 1 2 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

THE ICE BUILDUPS APPEAR TO HAVE BEEN CAUSED BY CONDENSATION. PRIOR TO.

EACH OCCURRENCE, THE ICE BED TEMPERATURE WAS DECREASING RESULTING IN

INCREASED INFLUX OF HUMID AIR. THIS WITH THE HIGHER HUMIDITY IN THE

SUMMER MONTHS RESULTED IN THE CONDENSATION WHICH FROZE STICKING THE

DOORS SHUT. DAILY INSPECTIONS HAVE NOT INDICATED ANY FURTHER PROBLEMS.

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 ROUTINE TOUR 32 DISCOVERY DESCRIPTION
7 8 9 10 12 13 44 45 46 80
16 ACTIVITY RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 44 45 80
17 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 11 12 13 80
18 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41
7 8 9 11 12 80
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 80
20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45
7 8 9 10 80

NAME OF PREPARER D. G. WIZNER

PHONE: 616-465-5901, EXT. 398

1944

1944