

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7911200358 DOC. DATE: 79/11/15 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH. NAME: SHALLER, D. V. AUTHOR AFFILIATION: Indiana & Michigan Power Co.
 RECIPIENT NAME: KEPPLER, J. G. RECIPIENT AFFILIATION: Region 3, Chicago, Office of the Director

SUBJECT: Confirms 791115 telcon w/RE Masse re power interruption. Due to removal of breaker, power interrupted from valves FMO-242 & FMO-212 for 12 minutes. Turbine-driven auxiliary feedwater pump also inoperable.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Incident Reports

NOTES: I&E - 3 CYS ALL MATERIAL

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
ACTION:	05 BC ORB #1	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANALYS	1	1
	29 AUX SYS BR	1	1	E JORDAN/IE	1	1
	HANAUER, S.	1	1	STS GROUP LEADR	1	1
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

NOV 21 1979

MA

TOTAL NUMBER OF COPIES REQUIRED: LTR 49 ENCL 0

60

[illegible]

1. **Содержание:** В документе содержится информация о результатах проведения работ по обеспечению безопасности жизнедеятельности населения в 2014 году.

[illegible]



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

November 15, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector,
Mr. R.E. Masse, at 1025 hours on November 15, 1979.

At that time we reported that due to the removal of a breaker,
power was interrupted from two FMO valves (FMO-242 and 212)
for a period of twelve (12) minutes. During this period the
Turbine Driven Auxiliary Feedwater Pump was also inoperable.

A followup report will be submitted by November 29, 1979, as
required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R.W. Kilburn
R.J. Vollen BPI
R.E. Masse RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.

J.M. Hennigan
G. Olson
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

Handwritten: 1002/10

Handwritten: 5 7911200 358