

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7911210446    DOC. DATE: 79/11/15    NOTARIZED: NO    DOCKET #  
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH. NAME: SHALLER, D.V.    AUTHOR AFFILIATION: Indiana & Michigan Power Co.  
 RECIP. NAME: KEPPLER, J.G.    RECIPIENT AFFILIATION: Region 3, Chicago, Office of the Director

SUBJECT: RO: on 791115, discovered isolated charging flow path of boron  
 injection tank of both inlet & outlet valves. Valve lineup  
 returned to SVS & Flow verified. Next rept will be submitted.

DISTRIBUTION CODE: A002S    COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Incident Reports

NOTES: SEND 3 CYS ALL MATH. TO J.E.E.

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	05 BC <u>ORB</u> 1	4		
INTERNAL:	<u>01 REG FILE</u>	1	02 NRC PDR	1
	09 I&E	2	11 MPA	3
	14 TA/EDO	1	15 NOVAK/KNIEL	1
	16 EEB	1	17 AD FOR ENGR	1
	18 PLANT SYS BR	1	19 I&C SYS BR	1
	20 AD PLANT SYS	1	22 REAC SAFT BR	1
	23 ENGR BR	1	24 KREGER	1
	25 PWR SYS BR	1	26 AD/SITE ANAL	1
	27 OPERA LIC BR	1	28 ACIDENT ANALYS	1
	29 AUX SYS BR	1	E JORDAN/IE	1
	HANAUER, S.	1	STS GROUP LEADR	1
	TMI-H STREET	1		
EXTERNAL:	03 LPDR	1	04 NSIC	1
	29 ACRS	16		

NOV 26 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR

51  
48

ENCL

0  
48

AOI  
4

GP

OVER 100 000



**INDIANA & MICHIGAN POWER COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106

November 15, 1979

Mr. J.G. Keppler, Regional Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-74  
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector, Mr. R.E. Masse, at 1035 hours on November 15, 1979.

At that time we reported that with the unit in Mode 6 the charging flow path was found isolated at the Boron Injection Tank at both inlet and outlet valves. Since the normal charging flow path was already isolated, this constituted an unavailable flow path. Upon discovery of this situation, we immediately returned the valve lineup to service and verified flow.

A followup report will be submitted by November 28, 1979, as required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller  
Plant Manager

/bab

cc: J.E. Dolan  
R.W. Jurgensen  
R.F. Kroeger  
R.W. Kilburn  
R.J. Vollen BPI  
R.E. Masse RO:III  
R.C. Callen MPSC  
P.W. Steketee, Esq.  
R. Walsh, Esq.  
G. Charnoff, Esq.

G. Olson  
J.M. Hennigan  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)

Approved  
5/10

7911210 446