

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7911300528 DOC. DATE: 79/11/15 NOTARIZED: NO DOCKET #  
 FACIC: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 ADTH. NAME AUTHOR AFFILIATION  
 SHALLER, D.V. Indiana & Michigan Power Co.  
 RECIPI. NAME RECIPIENT AFFILIATION

SUBJECT: RO-791115: on 791115, due to removal of breaker, power interrupted from FMO-242 & FMO-212 valves & turbine-driven auxiliary feedwater pump inoperable for 12 minutes. Followup rept to be submitted by 791129.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Incident Reports

NOTES: I & E - 3 CYS ALL MATL.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR
	05 BC ORB #1	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANLYS	1	1
	29 AOX SYS BR	1	1	E JORDAN/IE	1	1
	HANAUER, S.	1	1	STS GROUP LEADR	1	1
	TMI-H STREET	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

3.3/9

AOI  
4

TOTAL NUMBER OF COPIES REQUIRED: LTR 51 ENCL 0  
48

GD


THE NATIONAL BUREAU OF INVESTIGATION  
WASHINGTON, D. C. 20535

TO : DIRECTOR, FBI  
FROM : SAC, NEW YORK  
SUBJECT: [REDACTED]

RE: [REDACTED]

[REDACTED]

9707.2  
18  
010



**INDIANA & MICHIGAN POWER COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106

November 15, 1979

Mr. J.G. Keppler, Regional Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector,  
Mr. R.E. Masse, at 1025 hours on November 15, 1979.

At that time we reported that due to the removal of a breaker,  
power was interrupted from two FMO valves (FMO-242 and 212)  
for a period of twelve (12) minutes. During this period the  
Turbine Driven Auxiliary Feedwater Pump was also inoperable.

A followup report will be submitted by November 29, 1979, as  
required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller  
Plant Manager

/bab

cc: J.E. Dolan  
R.W. Jurgensen  
R.F. Kroeger  
R.W. Kilburn  
R.J. Vollen BPI  
R.E. Masse RO:III  
R.C. Callen MPSC  
P.W. Steketee, Esq.  
R. Walsh, Esq.  
G. Charnoff, Esq.

J.M. Hennigan  
G. Olson  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (40 copies)  
Dir., MIPC (4 copies)

NOV 19 1979

7911300528

4002  
5/10

